	UNITED STATES PARTMENT OF THE I REAU OF LAND MAN/	NTERIOR	MAY 27	N C Ex Ex S Cease Serial No.	DRM APPROVED MB No. 1004-0137 pires: July 31, 2010	
Do not use this	NOTICES AND REPO form for proposals to Use Form 3160-3 (Al	o drill or to re-en	er an	6. If Indian, Allottee or	Tribe Name	
SUBM	instructions on page 2	······	7. If Unit of CA/Agreement, Name and/or No. NMNM-78403A			
Oil Well Gas Well Other				8. Well Name and No. Northeast Hogback	8. Well Name and No. Northeast Hogback Unit #34	
2. Name of Operator Chuza Oil Company				9. API Well No. 30-045-09640		
3a. Address         3b. Phone No           1000 Cordova Place #376, Santa Fe, NM 87505         505-690-780			area code)	ea code) 10. Field and Pool or Exploratory Area Horseshoe Gallup		
4. Location of Well (Foolage, Sec., T., R., M., or Survey Description) 530' FSL 365' FWL Sec. 10 T30N R16W				11. Country or Parish, State San Juan County, New Mexico		
12. CHE	CK THE APPROPRIATE BO	X(ES) TO INDICATE N	ATURE OF NOT	ICE, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION			TYPE OF AC	TION		
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Constructi Plug and Abanc	on Rec	duction (Start/Resume) clamation complete nporarily Abandon ter Disposal	Water Shut-Off Well Integrity Other well communication	
On April 10th, 2014, Chuza Oil Con Hughes was contracted to provide fracturing operation was completed On the morning of April 14th, Chuz Unit #34. A sample of the gas esca observed to have a pressure readir It is Chuza's belief that the hydrauli Hogback Unit #31, which may have either plug and abandon it or perfor	hydraulic fracturing services at approximately 9pm on A a personnel performing a po ping from the Bradenhead v ng of 110psi. c fracturing operations on th e resulted in the pressure at	based on Chuza Oil ( pril 12th, and all frace post-frac field inspection valve was analyzed an e Northeast Hogback the Bradenhead of the	Company's 15-st quipment was m discovered pres d determined to Unit #74H possil	age treatment design. T loved off location on Ap sure on the Bradenhea be 91.348% nitrogen, a oly caused a casing or o back Unit #34. Chuza in	The last stage of hydraulic ril 13th. Ind valve of the Northeast Hogback Ind the Bradenhead valve was cement failure on the Northeast	
	···· • · · · · · · · · · · · · · · · ·		,		TED FOR RECORD	
				JL	IN 0 2 2014	
				FARMIN BY:	IGTON FIELD OFFICE	
14. I hereby certify that the foregoing is Name (Printed/Typed) Patrick Padilla	Title P	esident, Chuza	Oil Company			
Signature	m	Date 0	5/18/2014			
	THIS SPACE F	OR FEDERAL O	R STATE OF	FICE USE		
Approved by						
Conditions of approval, if any, are attache that the applicant holds legal or equitable entitle the applicant to conduct operations			e lice	D	ate	
entitle the applicant to conduct operations			<u> </u>			

