

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Lisa Hunter
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9786
Facility Name: Riddle 2A	Facility Type: Gas



Surface Owner BLM	Mineral Owner BLM	API No. 3004521990
--------------------------	--------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter C	Section 03	Township 30N	Range 09W	Feet from the 890'	North/South Line North	Feet from the 1460'	East/West Line West	County San Juan
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	-------------------------------	-------------------------------	---------------------------

Latitude **36.84503** Longitude **-107.77164**

NATURE OF RELEASE

Type of Release Produced Water Hydrocarbon	Volume of Release 6 BBLs Produced Water 7 BBLs Hydrocarbon	Volume Recovered 0 BBLs Produced Water 1.5 BBLs Hydrocarbon
Source of Release Ball Valve (Freeze)	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 12/30/13 @ 11:30 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? n/a	
By Whom? n/a	Date and Hour n/a	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. n/a	
If a Watercourse was Impacted, Describe Fully.* n/a	RCVD JAN 3 '14 OIL CONS. DIV. DIST. 3	
Describe Cause of Problem and Remedial Action Taken.* Ball valve froze and split down side spraying Produced Water (6 BBLs) and Hydrocarbon (7 BBLs). Release was contained within Berm, and 1.5 BBLs of Hydrocarbon recovered.		
Describe Area Affected and Cleanup Action Taken.* ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lisa Hunter	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 6/18/2014	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: December 31, 2013	Phone: (505) 326-9786	

* Attach Additional Sheets If Necessary

NSK1416931138