



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

RCVD JUN 24 '14

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV.

DIST. 3

Date of Test 24-Jun-2014 Operator CONOCO API #30-0 39 07704

Property Name SAN JUAN-6 Well No. 1 Location: Unit A Section 3 Township 29 Range 4

Well Status(Shut-In or Producing) Initial PSI: Tubing 119 Intermediate 0 Casing 116 Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	1	0	119	1	119
10 min	1	0	119	1	119
15 min	1	0	119	1	119
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	X
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

OPENED THE BRADENHEAD AND IT "PUFFED" TO NOTHING

OPENED THE INTERMEDIATE AND NOTHING CAME OUT

By [Signature]

Witness John D. [Signature]

(Position)

E-mail address _____