



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/23/2014 Operator Burlington API #30-0 39-07598
Property Name San Juan 29-7N Well No. 49 Location: Unit 2 Section 20 Township 29 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 119 Intermediate 122 Casing 125 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	D	4.5	123	D	125
10 min	D	4.5	124	0	125
15 min	D	4.7	124	0	126
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow			
Surges			
Down to Nothing			X
Nothing	X		
Gas			
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

OIL CONS. DIV DIST. 3

JUN 23 2014

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Intermediate blew down in 45 sec through 1" valve

By M. S. O.
(Position)

Witness Jonathan D. Kelly

E-mail address _____