

**NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3dstric.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/10/2014 Operator Burlington Resources API # 3003907259
Property Name SAN JUAN 28-5 UNIT Well No. 53 Location: Unit G Section 35 Township 028N Range 005W
Well Status Flowing Initial PSI: Tubing 222 Intermediate 2.3 Casing 222 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE					FLOW CHARACTERISTICS	
	BRADENHEAD			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 min		2.3	222		224	Steady Flow	
10 min		2.3	223		224	Surges	
15 min		2.3	223		225	Down to Nothing	Y
20 min						Nothing	Y
25 min						Gas	OIL CONS. DIV DIST. 3
30 min						Gas & Water	MAY 14 2014
						Water	

If Bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

If Intermediate flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE Bradenhead 0 Intermediate 0

REMARKS:

INT blew down in 26 sec thru 2" valve.

Tested By fiermg Witness _____