



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

RCVD AUG 19 '14

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV.

DIST. 3

Date of Test 8-19-14 Operator Energizer Res API #30-0 45-25002
Property Name Hilly Fed Well No. 1 Location: Unit 1 Section 29 Township 30 Range 15
Well Status (Shut-In or Producing) Initial PSI: Tubing 40 Intermediate N/A Casing 45 Bradenhead 57

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min			45		
10 min			45		
15 min	45		45		
20 min	5		45		
25 min	4		45		
30 min	4		45		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow	/	
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water	/	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 54

INTERMEDIATE N/A

REMARKS:

Run hose 1" ^{200' test} rolled to jet - started flowing at
1 min 30 seconds. - 5-10-15-20-25-30
flowed 3.74 barrels

By Eugene Burbank
Production Foreman
(Position)

Witness Monica Kuehling
Water Sample taken at BH & 1'
atch water

E-mail address _____