



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-17-14 Operator Burkington API #30-0 39-60102
Property Name San Juan 29-7 Well No. 56 Location: Unit Section 15 Township 29 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 216 Intermediate 230 Casing 230 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	0	230	231	217	202
10 min	0	230	231	210	205
15 min	0	230	231	204	198
20 min				200	194
25 min				196	191
30 min				192	187

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	✓
Surges	RCVD JUL 17 '14
Down to Nothing	OIL CONS. DIV.
Nothing	DIST 3
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 201

REMARKS:

BH - nothing when opened
Int. Very hard blow - casing dropping with
intermediate

By [Signature]

Witness

Monica Cuchlan
Request Gas analysis on Int.
Production Casing
Wellhead Schematic
box

(Position)

E-mail address