



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-15-14 Operator Burlington Res. API #30-0 45-27133

Property Name Allison Mt. Well No. 129 Location: Unit Section 16 Township 32 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate V/A Casing 8/10 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>10</u>		
10 min	<u>0</u>		<u>10</u>		
15 min	<u>0</u>		<u>10</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	<u>ROVD JUL 15 '14</u>
Down to Nothing	
Nothing	<u>OIL CONS. DIV.</u>
Gas	<u>DIST. 3</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE V/A

REMARKS:

Nothing when opened

By Mde Pena

Witness Monica Kuehl

(Position)

E-mail address