



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/28/2014 Operator Logos API # 30-043-21219

Property Name Logos Well No. 702H Location: Unit D Section 8 Township 22 Range 5

Well Status (Shut-In or Producing) Initial PSI: Tubing NA Intermediate NA Casing 200 Bradenhead -2.4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		300		
10 min	0		475		
15 min	0		500		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

OIL CONS. DIV DIST. 3

JUL 28 2014

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

AWS 395 on well. Intermediate string has been pulled for surface casing cement remediation
BH through 1/2 needle valve, BH had suction, down to nothing in 2 min 30 sec

By Jenny Brington
Lease Operator
(Position)

Witness

Jonathan D. Kelly

E-mail address _____