

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ARP Production Company, LLC	Contact	Randy L. Madison
Address	309 Silver St., Raton, NM 87740	Telephone No.	Office 575-445-6706 Cell 575-420-1120
Facility Name:	D-67	Facility Type:	Gas Well

Surface Owner	Vermejo Park Ranch	Mineral Owner	APR Production Company, LLC	API No.	30-007-20277
---------------	--------------------	---------------	-----------------------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	26	31N	17E	2,630	North	1265.44	West	Cofax

Latitude N 36 53 33.6679 Longitude W 105 06 41.2436

NATURE OF RELEASE

Type of Release : Produced Water	Volume of Release 8 Barrels	Volume Recovered : 0 Barrels
Source of Release: D-67 Stuffing Box	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 8/14/14 @ 1130
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Daniel Sanchez	
By Whom? Randy Madison	Date and Hour: 8/14/14 @ 1230	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. RCVD AUG 21 '14	

If a Watercourse was Impacted, Describe Fully.*

**OIL CONS. DIV.
DIST. 3**

Describe Cause of Problem and Remedial Action Taken.*

The stuffing box was leaking on the well head due to loose packings. The packings were tightened and lubricated. The spill did not leave the well pad.

Describe Area Affected and Cleanup Action Taken.*

The area will be monitored for staining and vegetation kill. If needed the soil will be excavated and disposed of properly. The area will be filled back in with original soil from the area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Randy L. Madison</i>		OIL CONSERVATION DIVISION	
Printed Name: Randy L. Madison		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: EHS Specialist		Approval Date: <i>8/26/14</i>	Expiration Date:
E-mail Address: rmadison@atlasenergy.com		Conditions of Approval:	
Date: 8/19/14	Phone: 575-445-6706	Attached <input type="checkbox"/>	

*Soil Samples 8015B 8021B
#NCS 1423840505 300.1*