

NEW MEXICO EMERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

RCVD AUG 20'14

OIL CONS. DIV.

BRADENHEAD TEST REPORT

DIST. 3

(submit 1 copy to above address)	
Date of Test 8, 20-14 Operato	or ENLYGEN (ED. API #30-0 39-24423
Date of Test 8' 20' 14 Operator MMYUW . API #30-0 39-24473 Property Name analy Well No. 15 Location: Unit Section 17 Township 32 Range 4	
Well Status (Shut-In or Producing) Initial PSI: Tubing 3 Intermediate (A Casing D Bradenhead 0	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 0 0	Steady Flow
10 min 0 0	Surges
15 min 0 0	Down to Nothing
20 min	Nothing
25 min	Gas
30 min	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY	SULFURBLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE A	
REMARKS: (acking when opened.	
By San Wolle Witness Mould Culdler	
(Position)	
Durall address	