

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: BP America Production Company	Contact: Courtney Cochran
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457
Facility Name: Shane GC 1B	Facility Type: Natural Gas Well

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3004530108
------------------------	------------------------	---------------------

**LOCATION OF RELEASE**

Unit Letter M	Section 14	Township 29N	Range 09W	Feet from the 910	North/South Line South	Feet from the 660	East/West Line West	County: San Juan
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	------------------

Latitude 36.72034 Longitude 107.75522

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 9 bbls	Volume Recovered: 95 bbls were recovered from the BGT – recovered fluid was a mix of rain water and produced water
Source of Release: 95 bbl BGT	Date and Hour of Occurrence: 9/22/2013	Date and Hour of Discovery: 9/23/2013
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	<b>RCVD NOV 1 '13</b>
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>OIL CONS. DIV.</b>	
<b>DIST. 3</b>		

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

During a rain storm event rain run-off from the mesa above the location created a drainage ditch that ran through location and flooded the BGT. Estimated volume in BGT before event 9 bbls taken from last gauge on 9/14/2013. The BGT is a 95 bbl BGT and was full after rain event occurred. The 95 bbls of fluid were pulled after the discovery was made.

Describe Area Affected and Cleanup Action Taken.\*

All fluid released was contained on location. The produced water did have a slight oil sheen and a visible stain is present. Impacted soil will be remediated when erosion repair takes place. Erosion repair and remediation are currently being planned.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Courtney Cochran	Approved by Environmental Specialist: 	
Title: Field Environmental Advisor	Approval Date: <u>8/27/2014</u>	Expiration Date:
E-mail Address: <u>Courtney.Cochran@bp.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/30/2013 Phone: 505-326-9457		

\* Attach Additional Sheets If Necessary

NJK 14 23954360