

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Lisa Hunter
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9786
Facility Name: Grambling C #7	Facility Type: Gas Well

Surface Owner BLM	Mineral Owner BLM	API No. 3004520671
--------------------------	--------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter A	Section 12	Township 30N	Range 10W	Feet from the 890	North/South Line North	Feet from the 1000'	East/West Line East	County Rio Arriba
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	-------------------------------	-------------------------------	-----------------------------

Latitude 36.83124 Longitude -107.83026

NATURE OF RELEASE

Type of Release Lube Oil	Volume of Release 7.38 BBL	Volume Recovered 5 BBL
Source of Release Day Tank	Date and Hour of Occurrence 07/14/14 @ 12:24 p.m.	Date and Hour of Discovery 07/14/14 @ 12:24 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? OIL CONS. DIV DIST. 3	
By Whom?	Date and Hour JUL 18 2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

While contractor was filling 500 gallon lube oil Day Tank, tank over pressurized and breached seam (northeast edge), releasing 7.38 BBLs of lube oil into and outside of bermed area. Release remained on location. Truck was called and removed standing fluids, recovering approximately 5 BBLs. Will hydrovac remaining contamination.

Describe Area Affected and Cleanup Action Taken.*

ConocoPhillips will hydrovac effected area to remove contaminated soil and assess the soil via third-party environments to meet NMOCD regulatory standards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Approved by Environmental Specialist:

Printed Name: **Lisa Hunter**

Title: **Field Environmental Specialist**

Approval Date: **9/5/14**

Expiration Date:

E-mail Address: **Lisa.Hunter@cop.com**

Conditions of Approval:

Attached ☐

Date: **July 16, 2014** Phone: **(505) 326-9786**

* Attach Additional Sheets If Necessary

#NCS 1424852021

①