



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-9-14 Operator Burlington API #30-0 39-23501
Property Name SS 30-6 W. SW 1/4 Well No. 1124 Location: Unit 26 Section 26 Township 30 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 349 Intermediate 0 Casing -9 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	0	0	-9	0	-9
10 min	0	0	-9	0	-9
15 min	0	0	-9	0	-9
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing	✓	
Gas		✓
Gas & Water		
Water		

DIST. 3

OIL CONS. DIV.

RCVD SEP 9 '14

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH nothing when opened
Int. dead at 1.5 min (liquid blow)

By [Signature]
SUD 450
(Position)

Witness

[Signature]

E-mail address _____