



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

## MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 9-9-14 Operator Burlington Res API # 30-0 59-23501

Property Name SJ30-6W SWD Well # 1124 Location: Unit 26 Twn 30 Rge 6

Land Type:

State             
Federal             
Private             
Indian           

Well Type:

Water Injection             
Salt Water Disposal ☒  
Gas Injection             
Producing Oil/Gas             
Pressure observation           

Temporarily Abandoned Well (Y/N): (N)

TA Expires:           

DIST. 3

Casing Pres. 0  
Bradenhead Pres. 0  
Tubing Pres. 337  
Int. Casing Pres. 0

Tbg. SI Pres. 337  
Tbg. Inj. Pres.           

Max. Inj. Pres.             
OIL CONS. DIV.

Pressured annulus up to 570 psi. for 30 mins. Test passed/failed

RCVD SEP 9 '14

REMARKS:

Packer set at 8172

top of 8221

Rose to 580 & held last 10 min

By D. J. [Signature]  
(Operator Representative)

Witness

Monica Cuchling  
(NMOCD)

SWD M50  
(Position)

Chauf. stuck at 2165 bled off at well head

Revised 02-11-02