

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP America Production Company	Contact: Courtney Cochran	
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457	
Facility Name: Wilch A5	Facility Type: Natural Gas Well	
Surface Owner: Federal	Mineral Owner: Federal	API No.: 3004523343

LOCATION OF RELEASE

Unit Letter L	Section 23	Township T29N	Range R08W	Feet from the 2450	North/South Line South	Feet from the 1160	East/West Line West	County: San Juan
------------------	---------------	------------------	---------------	-----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 36.71057 Longitude 107.65059



NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 527 MCF	Volume Recovered: none
Source of Release: Water Dump Valve on Separator	Date and Hour of Occurrence: 8/6/2014 - 8/11/2014	Date and Hour of Discovery: 8/11/2014 - 10:45 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith - NMOCD & Shari Ketcham - BLM	
By Whom? Courtney Cochran - BP	Date and Hour: 8/14/2014 - 1:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. OIL CONS. DIV DIST. 3	
If a Watercourse was Impacted, Describe Fully.* AUG 25 2014		

Describe Cause of Problem and Remedial Action Taken.*
Field technician arrived on location to check an automation code and found gas blowing by the trim set on the water dump valve of the separator. Upon further investigation found trash in the seat which allowed gas blow by.

Describe Area Affected and Cleanup Action Taken.*
Well is currently shut-in. No clean-up action possible. Natural gas dissipated to the atmosphere.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by Environmental Specialist: 	
Title: Environmental Advisor	Approval Date: <u>8/26/14</u>	Expiration Date:
E-mail Address: <u>Courtney.Cochran@bp.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/14/2014 Phone: 505-326-9457		

* Attach Additional Sheets If Necessary

#142 384 0730