

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

1					-		·				
Date of Test	9-11-07		Operator		Patina San Juan, Inc.			ΛΡΙ# 	3003906330		
Property Nam			ILLA B 1		Locatio	on: Unit B	Section 26 T	ownship	26	Range	4
		(Well Name	and Number)								
Pressure (Sh	ut-in or Proc	lucing)	Tubing <u>2</u>	06	Interme	diate	Casing 2	10 Br	adenh	ead <u>~</u>	2
OPE	N BRADENH	EAD AND	INTERMEDIA	TE TO	ATMOSI	PHERE IND	IVIDUALLY FOR	15 MINU	TES E	ACH	
1	Bradenhead			Intermediate				Brader	head	Interme	adiato
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor		termediate Blowdown	Casing Monitor		Flow		Flow	
5 minutes	-0	in onitor	inomicor .		,,owaowii	inomio.	Steady Flow				
10:minutes	-0						Surges				
15 minutes		<u> </u>		-			Down to Nothing				
20 minutes		<u> </u>		-			No Flow	X			
25 minutes						 	Gas				
30 minutes							Gas and Water				
5 minute SI						 	Water				
If bradenh Clear 5 Minute S REMARKS:	F	resh _	Sa	ty	mediate	Sulfur		9202122		. 83	
							1	(110,		E 15	
								98	Z99°		
ву Сп	og Vig	1	n Uf)	W	itness					
LE	OP PUR	PER									•
		(Positio	n)								