



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9-11-07 Operator Patina San Juan, Inc. API # 3003906592

Property Name MCINTYRE 1 Location: Unit F Section 11 Township 26 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) 75 Intermediate — Casing 78 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	<u>0</u>	<u>78</u>	<u>—</u>									
10 minutes												
15 minutes												
20 minutes												
25 minutes												
30 minutes												
5 minute SI												

	Bradenhead Flowed	Intermediate Flowed
Steady Flow		
Surges		
Down to Nothing	<u>X</u>	
No Flow		
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear — Fresh — Salty — Sulfur — Black —

5 Minute Shut-in Bradenhead 0 Intermediate —

REMARKS:

By Greg Vigil
LEAD PUMPER
(Position)

Witness _____

