



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9-18-07 Operator Patina San Juan, Inc. API # 3003906651

Property Name HURON 1 Location: Unit M Section 2 Township 26 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 72 Intermediate — Casing 77 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>0</u>	<u>77</u>	<u>—</u>			Steady Flow		
10 minutes						Surges		
15 minutes						Down to Nothing		
20 minutes						No Flow	<u>X</u>	<u>—</u>
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear — Fresh — Salty — Sulfur — Black —

5 Minute Shut-in Bradenhead 0 Intermediate —

REMARKS:



By Greg Vigil - Sig Up Witness _____
LEAD PUMPER
(Position)