



**NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 9-18-07 Operator Patina San Juan, Inc. API # 3003906750

Property Name HURON 3 Location: Unit E Section 5 Township 26 Range 4  
(Well Name and Number)

Pressure Shut-in or Producing Tubing 65 Intermediate — Casing 68 Bradenhead —

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead		
	BH Blowdown	Casing Monitor	Intermediate Monitor
5 minutes	<u>—</u>	<u>68</u>	<u>—</u>
10 minutes			
15 minutes			
20 minutes			
25 minutes			
30 minutes			
5 minute SI			

Intermediate	
Intermediate Blowdown	Casing Monitor

Bradenhead Flowed	Intermediate Flowed
Steady Flow	
Surges	
Down to Nothing	
No Flow	<u>X</u>
Gas	
Gas and Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear — Fresh — Salty — Sulfur — Black —

5 Minute Shut-in Bradenhead — Intermediate —

**REMARKS:**



By Greg Vigil - Greg Vigil Witness —

LEAD PUMPER

(Position)