



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9-11-07 Operator Patina San Juan, Inc. API # 3003907126

Property Name NORTHWEST 1 Location: Unit G Section 7 Township 26 Range 4
(Well Name and Number)

Pressure (Shut-in) or Producing Tubing 139 Intermediate — Casing 142 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>142</u>	<u>—</u>			Steady Flow	
10 minutes						Surges	
15 minutes						Down to Nothing	
20 minutes						No Flow	<u>X</u>
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear — Fresh — Salty — Sulfur — Black —

5 Minute Shut-in Bradenhead 0 Intermediate —

REMARKS:

By Greg Vigil - Bug Up Witness _____
LEAD PUMPER
(Position)

