

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

i			(Gubiiii	. z oopioo to un	ovo adaro			
Date of Test	of Test $9-18-07$ Operato		Operator	Patina	Inc. A	API# 300	03921345	
Property Nam	e	JICARILLA C 1A			Location: Unit A Section		ownship 26	Range 4
1		(Well Name	and Number)					
Pressure (Sh	ut-in or Prod	lucing	Tubing	72 Interme	diate	Casing 1	36 Bradenh	nead <u> </u>
OPEN	I BRADENHI	EAD AND	INTERMEDIA	TE TO ATMOSF	PHERE IND	IVIDUALLY FOR	15 MINUTES E	ACH
	Bradenhead			Intermediate			Bradenhead	Intermediate
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	0	136	•			Steady Flow		
10 minutes		130				Surges		
15 minutes						Down to Nothing		
20 minutes						No Flow	X	
25 minutes						Gas		
30 minutes						Gas and Water		<u> </u>
5 minute SI						Water		
If bradenho	F	resh _	Sal	escriptions that ty Intermediate	Sulfur		ck Sept 1819202 Sept 1819202	2122232 25 25 25 25 25 25 25 25 25 25 25 25 25
		.1.	29 6	10 m	4		~~~	
By GY	eg Vig 40 Pun	per	ny	~ WI	tness			

(Position)