



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9-11-07 Operator Patina San Juan, Inc. API # 3003921618

Property Name NORTHWEST 1A Location: Unit 0 Section 7 Township 26 Range 4

(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 47 Intermediate — Casing 179 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>179</u>	<u>—</u>				
10 minutes							
15 minutes							
20 minutes							
25 minutes							
30 minutes							
5 minute SI							

Steady Flow		
Surges		
Down to Nothing	<u>X</u>	
No Flow		
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 5 Intermediate —

REMARKS:

By Greg Vail - Greg Vail
LEAD PUMPER

(Position)

Witness _____

