

(Position)

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			(0		- p		,			
Date of Test	9-24-07 Operator			<u></u>	Patina	Inc.	API#	300	3927663	
Property Name	HOYT 2C				Location: Unit O Section 5			ownship	26	Range 4
		(Well Name	and Number)		- 					
Pressure (Shu	t-in o Proc	lucing	Tubing	41	_ Interme	diate	Casing <u>5</u>	<u>3</u> Br	adenh	ead <u>O</u>
OPEN	BRADENH	EAD AND	INTERMEDIA	TE T		PHERE IND	IVIDUALLY FOR	15 MINU	TES E	ACH
Γ	Bradenhead				Interme	ediate		Braden	head	Intermediate
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	۱	ntermediate Blowdown	Casing Monitor		Flow		Flowed
5 minutes	- O	53		-	<u> </u>	Wild the state of	Steady Flow			
10 minutes		<u> </u>		-			Surges			
15 minutes				-		 	Down to Nothing			
20 minutes				-		 	No Flow	X		***************************************
25 minutes			i	-			Gas	•		
30 minutes				-			Gas and Water	-		
5 minute SI				-			Water			
If bradenher Clear 5 Minute Sh	F	resh	Sal	ty	iptions that	t apply bel	Bla 21314/k	6118192		ED 8
								565	<u> + € Z \</u>	
By Gre	es Vigi to Pur	npep	Jug ()	2	Wi	itness				