



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9-1-07 Operator Patina San Juan, Inc. API # 3003929256

Property Name HOYT 1B Location: Unit C Section 5 Township 26 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 160 Intermediate - Casing 345 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>345</u>	<u>-</u>				
10 minutes							
15 minutes							
20 minutes							
25 minutes							
30 minutes							
5 minute SI							
						Steady Flow	
						Surges	
						Down to Nothing	
						No Flow	<u>X</u>
						Gas	<u>-</u>
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate

REMARKS:

By Greg Vigil - LG Witness _____
LEAD PUMPER
(Position)

