



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9-19-07 Operator Patina San Juan, Inc. API # 3003906633

Property Name JICARILLA 3 Location: Unit B Section 8 Township 26 Range 5  
(Well Name and Number)

Pressure (Shut-in) or Producing) Tubing 63 Intermediate — Casing 67 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate		
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes	<u>0</u>	<u>67</u>	<u>—</u>			Steady Flow			
10 minutes						Surges			
15 minutes						Down to Nothing			
20 minutes						No Flow	<u>X</u>	<u>—</u>	
25 minutes						Gas			
30 minutes						Gas and Water			
5 minute SI						Water			

If bradenhead flowed water, check all of the descriptions that apply below:

Clear — Fresh — Salty — Sulfur — Black —

5 Minute Shut-in Bradenhead 0 Intermediate —

REMARKS:

By Greg Vigil - LEAD PUMPER  
(Position)

Witness —

