

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ARP Production Company, LLC	Contact	Randy L. Madison
Address	309 Silver St., Raton, NM 87740	Telephone No.	Office 575-445-6706 Cell 575-420-1120
Facility Name	VPR B-26	Facility Type	Gas Well

Surface Owner	Vermejo Park Ranch	Mineral Owner	APR Production Company, LLC	API No.	30-007-20082
---------------	--------------------	---------------	-----------------------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	25	30N		2413'	North	1324	East	Colfax

Latitude N 36 48 22.3604 Longitude W 104 58 34.6494 **RCVD SEP 16 '14**

NATURE OF RELEASE

OIL CONS. DIV.



Type of Release	Produced Water	Volume of Release	8.5 Barrels	Volume Recovered	0
Source of Release	Loose Hammer union on 2" line	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	9/5/14 @ 1204
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? DIST. 3			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Hammer union was loose on a 2" produced water line. The union was tightened.

Describe Area Affected and Cleanup Action Taken.*
The area will be monitored for vegetation kill. If that happens the area will be excavated and contaminated soil disposed of properly. The leak did not leave the well pad.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Randy L. Madison		Approved by Environmental Specialist: 	
Title: EHS Specialist	Approval Date: 9/18/14	Expiration Date:	
E-mail Address: rmadison@atlasenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 9/8/14	Phone: 575-445-6706		

#NCS 1426131865

①