

1625 First Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: XTO Energy, Inc.	Contact: Kurt Hoekstra	
Address: 382 Road 3100, Aztec, New Mexico 87410	Telephone No.: (505) 333-3100	
Facility Name: Jack Frost Gas Com C # 1E	Facility Type: Gas Well (Basin Dakota)	
Surface Owner: Federal	Mineral Owner	API No.: 30-045-25783

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	26	27N	10W	1520	FNL	450	FEL	San Juan

Latitude 36.54786 Longitude -107.85792

NATURE OF RELEASE

Type of Release: Condensate/ Produced Water	Volume of Release: 5 BBL Condensate, 13 BBL Produced Water	Volume Recovered: None
Source of Release: Production Tank	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: August 25, 2014 12:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? RCVD SEP 11 '14 OIL CONS. DIV. DIST. 3	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* On Monday, 8/25/14, an XTO lease operator discovered a corrosion hole approximately 2" up from the bottom of the production tank on the Jack Frost C#1E location. 13 BBL produced water and 5 BBL condensate seeped into the ground inside the tank berm, confirming that a release has occurred at this location. The site was then ranked according to the NMOCD Guidelines for the Remediation of Leaks, Spills and Releases. The site was ranked a 0 due to an estimated depth to groundwater of more than 100 feet, distance to a water well greater than 1000 feet, and distance to surface water greater than 1000 feet. This set the closure standard to 5000 ppm TPH, 10 ppm benzene, and 50 ppm total BTEX.

Describe Area Affected and Cleanup Action Taken.* A remediation plan was submitted and clean-up is underway.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kurt Hoekstra</i>		OIL CONSERVATION DIVISION	
Printed Name: Kurt Hoekstra		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: EHS Coordinator	Approval Date: 9/8/14	Expiration Date:	
E-mail Address: Kurt.Hoekstra@xtoenergy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 9-5-2014	Phone: 505-333-3100		

* Attach Additional Sheets If Necessary

HNCS 1426139723

①