

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Lisa Hunter
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9786
Facility Name: Blanco Unit 202A	Facility Type: Gas Well
Surface Owner BLM	Mineral Owner BLM
API No. 3004532262	

LOCATION OF RELEASE



Unit Letter I	Section 26	Township 31N	Range 08W	Feet from the 2000	North/South Line FSL	Feet from the 700	East/West Line East	County San Juan
-------------------------	----------------------	------------------------	---------------------	------------------------------	--------------------------------	-----------------------------	-------------------------------	---------------------------

Latitude 36.83714 Longitude -107.63768

RCVD SEP 11 '14
OIL CONS. DIV.

NATURE OF RELEASE

DIST. 3

Type of Release Produced Water	Volume of Release 5 BBL	Volume Recovered 0 BBL
Source of Release Transfer pump	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 09/05/14 @ 4:30 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* One inched nipple on discharge of transfer pump broke while pump was running, causing the release of 5 bbls Produced Water. Release remained contained in bermed area. Pump shut off and isolated.		
Describe Area Affected and Cleanup Action Taken.* ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lisa Hunter	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 9/18/14	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: September 8, 2014 Phone: (505) 326-9786		

* Attach Additional Sheets If Necessary

#NCS 1426136928

①