

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company EnerVest Operating	Contact Michael Dame
Address 2700 Farmington Ave. Building K, Suite 1	Telephone No. 505-325-0318
Facility Name Jicarilla 35 A Gas Com #001 E	Facility Type Oil Well

Surface Owner Jicarilla Apache Nation	Mineral Owner Jicarilla Apache Nation	API No. 30-039-22173
---------------------------------------	---------------------------------------	----------------------

LOCATION OF RELEASE

RCVD SEP 23 '14

Unit Letter J	Section 11	Township 24N	Range 5N	Feet from the	North/South Line	Feet from the	East/West Line	County Rio Arriba
------------------	---------------	-----------------	-------------	---------------	------------------	---------------	----------------	----------------------

Latitude 36.323762 Longitude -107.327971

OIL CONS. DIV.

DIST. 3

NATURE OF RELEASE

Type of Release Oil, Produced Water	Volume of Release Unknown	Volume Recovered None
Source of Release 400 bbl oil tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 8/28/2014 1:00pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



Small hole in tank bottom, allowed contents to leak out over an unknown period of time.

Describe Area Affected and Cleanup Action Taken.*

Tank has been removed. And excavation of impacted soil is taking place. Impacted soil will be transported to TNT Land Farm. Back Fill will be obtained from Jicarilla Apache approved location.

Jicarilla Apache Environmental Officer was notified.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Michael Dame	Approved by Environmental Specialist: 	
Title: HSE Associate	Approval Date: 9/23/14	Expiration Date:
E-mail Address: mdame@enervest.net	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/3/14	Phone: 505-325-0318	

* Attach Additional Sheets If Necessary

#NCS 142 6651 825

①