



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III3district.htm](http://emnr.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-24-14 Operator Emr Vest LLC API #30-045-33982

Property Name Rio Bravo 27 Well No. 12 Location: Unit L Section 27 Township 31N Range 13W

Well Status (Shut-In or Producing) Initial PSI: Tubing 170 Intermediate n/a Casing 100 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>100</u>		
10 min	<u>0</u>		<u>100</u>		
15 min	<u>0</u>		<u>100</u>		
20 min	<u>0</u>		<u>100</u>		
25 min	<u>0</u>		<u>100</u>		
30 min	<u>0</u>		<u>100</u>		

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow _____ RCVD OCT 17 '14
Surges _____ OIL CONS. DIV.
Down to Nothing _____ DIST. 3
Nothing _____ X
Gas _____
Gas & Water _____
Water _____

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE n/a

REMARKS:

By Ry Pm
Pumper
(Position)

Witness _____

E-mail address _____