District I
1625 N. French Dr., Hobbs, NM 88240
District II \
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505
,

State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For temporary pits, below-grade tanks, and multi-well fluid management pits, submit to the appropriate NMOCD District Office. For permanent pits submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

Pit, Below-Grade Tank, or
12239 Proposed Alternative Method Permit or Closure Plan Application
Type of action: $\square$ Below grade tank registrationPermit of a pit or proposed alternative methodPCUD SEP 30 '14 $U3 - 21156$ $\square$ Closure of a pit, below-grade tank, or proposed alternative method $\square$ OIL CONS. DIV. $\square$ Modification to an existing permit/or registration $\square$ DIST. 3 $\square$ or proposed alternative method $\square$ or proposed alternative method
A meredeo Instructions: Please submit one application (Form C-144) per individual pit, below-grade tank or alternative request
Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.
1. Operator: LOGOS OPERATING, LLC OGRID #: 289408
Address: 4001 NORTH BUTLER AVENUE, BUILDING 7101 FARMINGTON NM 87401
Facility or well name: LOGOS 8
API Number: 30-043-21156 OCD Permit Number: 11411
U/L or Qtr/QtrG Section5 Township22N Range _5W County: SANDOVAL
Center of Proposed Design: Latitude _36.16917° N Longitude _107.38330° W NAD: 1927 🛛 1983
Surface Owner: 🗌 Federal 🗋 State 🗋 Private 🖾 Tribal Trust or Indian Allotment
2. ∑ Pit: Subsection F, G or J of 19.15.17.11 NMAC
Temporary: $\square$ Drilling $\square$ Workover
Permanent Emergency Cavitation P&A Multi-Well Fluid Management Low Chloride Drilling Fluid yes in no
$\square$ Lined $\square$ Unlined Liner type: Thickness $\_20$ mil $\square$ LLDPE $\square$ HDPE $\square$ PVC $\square$ Other
String-Reinforced
Liner Seams: 🛛 Welded 🖾 Factory 🗌 Other Volume: 8,000 bbl Dimensions: L 130 x W 60 x D 10
3. Below-grade tank: Subsection 1 of 19.15.17.11 NMAC
Volume:bbl Type of fluid:
Tank Construction material:
Secondary containment with leak detection 🔲 Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off
Visible sidewalls and liner Visible sidewalls only Other
Liner type: Thicknessmil 🔲 HDPE 🗋 PVC 🗋 Other
4.       Alternative Method:
Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.
<ul> <li>s.</li> <li>Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks)</li> <li>Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, hospital,</li> </ul>
<ul> <li>institution or church)</li> <li>Four foot height, four strands of barbed wire evenly spaced between one and four feet</li> <li>Alternate. Please specify 4' HOG WIRE WITH ONE STRAND OF BARBED WIRE ON TOP.</li> </ul>

Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks)

Screen Netting Other

6

7.

Monthly inspections (If netting or screening is not physically feasible)

#### Signs: Subsection C of 19.15.17.11 NMAC

12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers

Signed in compliance with 19.15.16.8 NMAC

#### Variances and Exceptions:

Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance.

Please check a box if one or more of the following is requested, if not leave blank:

Variance(s): Requests must be submitted to the appropriate division district for consideration of approval.

Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.

Siting Criteria (regarding permitting): 19.15.17.10 NMAC

Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptable source material are provided below. Siting criteria does not apply to drying pads or above-grade tanks.

General siting	
<u>Ground water is less than 25 feet below the bottom of a low chloride temporary pit or below-grade tank.</u> - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	□ Yes □ No □ NA
Ground water is less than 50 feet below the bottom of a Temporary pit, permanent pit, or Multi-Well Fluid Management pit. NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
<ul> <li>Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. (Does not apply to below grade tanks)</li> <li>Written confirmation or verification from the municipality; Written approval obtained from the municipality</li> </ul>	🗌 Yes 🗌 No
Within the area overlying a subsurface mine. (Does not apply to below grade tanks) - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	Yes No
<ul> <li>Within an unstable area. (Does not apply to below grade tanks)</li> <li>Engineering measures incorporated into the design; NM Bureau of Geology &amp; Mineral Resources; USGS; NM Geological Society; Topographic map</li> </ul>	🗌 Yes 🗌 No
Within a 100-year floodplain. (Does not apply to below grade tanks) - FEMA map	Yes No
Below Grade Tanks	
<ul> <li>Within 100 feet of a continuously flowing watercourse, significant watercourse, lake bed, sinkhole, wetland or playa lake (measured from the ordinary high-water mark).</li> <li>Topographic map; Visual inspection (certification) of the proposed site</li> </ul>	🗌 Yes 🗌 No
<ul> <li>Within 200 horizontal feet of a spring or a fresh water well used for public or livestock consumption;.</li> <li>NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site</li> </ul>	🗌 Yes 🗌 No
Temporary Pit using Low Chloride Drilling Fluid (maximum chloride content 15,000 mg/liter)	
<ul> <li>Within 100 feet of a continuously flowing watercourse, or any other significant watercourse or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). (Applies to low chloride temporary pits.)</li> <li>Topographic map; Visual inspection (certification) of the proposed site</li> </ul>	🗋 Yes 🗌 No
<ul> <li>Within 300 feet from a occupied permanent residence, school, hospital, institution, or church in existence at the time of initial application.</li> <li>Visual inspection (certification) of the proposed site; Aerial photo; Satellite image</li> </ul>	🗌 Yes 🗌 No
Within 200 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 300feet of any other fresh water well or spring, in existence at the time of the initial application.	Yes 🗌 No

<ul> <li>Within 100 feet of a wetland.</li> <li>US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site</li> </ul>	🗌 Yes 🗌 No						
Temporary Pit Non-low chloride drilling fluid							
<ul> <li>Within 300 feet of a continuously flowing watercourse, or any other significant watercourse, or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).</li> <li>Topographic map; Visual inspection (certification) of the proposed site</li> </ul>	🗋 Yes 🗌 No						
<ul> <li>Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.</li> <li>Visual inspection (certification) of the proposed site; Aerial photo; Satellite image</li> </ul>	🗌 Yes 🗌 No						
<ul> <li>Within 500 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 1000 feet of any other fresh water well or spring, in the existence at the time of the initial application;</li> <li>NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site</li> </ul>	🗌 Yes 🗍 No						
<ul> <li>Within 300 feet of a wetland.</li> <li>US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site</li> </ul>	Yes No						
Permanent Pit or Multi-Well Fluid Management Pit							
<ul> <li>Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).</li> <li>Topographic map; Visual inspection (certification) of the proposed site</li> </ul>	🗌 Yes 🗌 No						
<ul> <li>Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.</li> <li>Visual inspection (certification) of the proposed site; Aerial photo; Satellite image</li> </ul>	🗌 Yes 🗌 No						
<ul> <li>Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.</li> <li>NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site</li> </ul>	🗌 Yes 🗌 No						
<ul> <li>Within 500 feet of a wetland.</li> <li>US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site</li> </ul>	🗌 Yes 🗌 No						
10.         Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 N         Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the doc attached. <ul> <li>Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC</li> <li>Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC</li> <li>Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC</li> <li>Design Plan - based upon the appropriate requirements of 19.15.17.10 NMAC</li> <li>Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC</li> <li>Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.13 NMAC</li> <li>Previously Approved Design (attach copy of design) API Number: or Permit Number:</li> </ul>	cuments are NMAC 15.17.9 NMAC						
Multi-Well Fluid Management Pit Checklist:       Subsection B of 19.15.17.9 NMAC         Instructions:       Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the doc attached. <ul> <li>Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC</li> <li>Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC</li> <li>A List of wells with approved application for permit to drill associated with the pit.</li> <li>Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.</li> </ul> and 19.15.17.13 NMAC <ul> <li>Hydrogeologic Data - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.10 NMAC</li> <li>Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC</li> <li>Previously Approved Design (attach copy of design)</li> <li>API Number:</li></ul>	15.17.9 NMAC						

12. <u>Permanent Pits Permit Application Checklist</u> : Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the	documents are
attached. <ul> <li>Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC</li> <li>Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC</li> <li>Climatological Factors Assessment</li> <li>Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC</li> <li>Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC</li> <li>Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC</li> <li>Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC</li> <li>Quality Control/Quality Assurance Construction and Installation Plan</li> <li>Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.11 NMAC</li> <li>Nuisance or Hazardous Odors, including H<sub>2</sub>S, Prevention Plan</li> <li>Emergency Response Plan</li> <li>Oil Field Waste Stream Characterization</li> <li>Monitoring and Inspection Plan</li> <li>Erosion Control Plan</li> <li>Closure Plan - based upon the appropriate requirements of 19.15.17.9 NMAC and 19.15.17.13 NMAC</li> </ul>	
<u>Proposed Closure</u> : 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.	
Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Multi-well F Alternative Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial On-site Trench Burial Alternative Closure Method	luid Management Pit
<ul> <li>Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be closure plan. Please indicate, by a check mark in the box, that the documents are attached.</li> <li>Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC</li> <li>Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.13 NMAC</li> <li>Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings)</li> <li>Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC</li> <li>Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC</li> </ul>	
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable sour provided below. Requests regarding changes to certain siting criteria require justifications and/or demonstrations of equivalency. I 19.15.17.10 NMAC for guidance.	
<ul> <li>Ground water is less than 25 feet below the bottom of the buried waste.</li> <li>NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells</li> </ul>	☐ Yes ☐ No ☐ NA
<ul> <li>Ground water is between 25-50 feet below the bottom of the buried waste</li> <li>NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells</li> </ul>	□ Yes □ No □ NA
<ul> <li>Ground water is more than 100 feet below the bottom of the buried waste.</li> <li>NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells</li> </ul>	□ Yes □ No □ NA
<ul> <li>Within 100 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).</li> <li>Topographic map; Visual inspection (certification) of the proposed site</li> </ul>	🗌 Yes 🗌 No
<ul> <li>Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.</li> <li>Visual inspection (certification) of the proposed site; Aerial photo; Satellite image</li> </ul>	🗌 Yes 🗌 No
<ul> <li>Within 300 horizontal feet of a private, domestic fresh water well or spring used for domestic or stock watering purposes, in existence at the time of initial application.</li> <li>NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site</li> </ul>	🗌 Yes 🗍 No
Written confirmation or verification from the municipality; Written approval obtained from the municipality	🗌 Yes 🗌 No
Within 300 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	🗌 Yes 🗋 No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance	

adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	Yes No
<ul> <li>Wishin the area overlying a subsurface mine.</li> <li>Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division</li> </ul>	🗌 Yes 🗌 No
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological	
Society; Topographic map	🔲 Yes 🗌 No
Within a 100-year floodplain. - FEMA map	🗌 Yes 🗌 No
On-Site Closure Plan Checklist:       (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure properties of the box, that the documents are attached.         Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC         Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection E of 19.15.17.13 NMAC         Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of Subsection K of 19.15.17         Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19.15.17.13 NMAC         Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC         Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of 19.15.17.13 NMAC         Waste Material Sampling Plan - based upon the appropriate requirements of 19.15.17.13 NMAC         Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cant         Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC         Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC         Site Reclamation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC         Image: the system of the appropriate requirements of Subsection H of 19.15.17.13 NMAC         Image: the system of the appropriate requirements of Subsection H of 19.15.17.13 NMAC	.11 NMAC .15.17.11 NMAC
Operator Application Certification:           I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and below	lief.

Name (Print): Title:	
Signature: Date:	
e-mail address: Telephone:	
18.       OCD Approval:       Permit Application (including closure plan)       Image: Closure Plan (only)       OCD Conditions (see at OCD Representative Signature:         OCD Representative Signature:       OCD Representative Signature:       Approval Description         Title:       Compliance       OCD Permit Number:	ate: 10/27/524
<sup>19.</sup> <u>Closure Report (required within 60 days of closure completion)</u> : 19.15.17.13 NMAC Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities a The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. section of the form until an approved closure plan has been obtained and the closure activities have been completed. Closure Completion Date: 5/8/1	Please do not complete this
20. Closure Method: □ Waste Excavation and Removal ⊠ On-Site Closure Method □ Alternative Closure Method □ Waste Remo □ If different from approved plan, please explain.	val (Closed-loop systems only)
21.         Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report mark in the box, that the documents are attached.	

ł

## **Operator Closure Certification:**

22.

I hereby certify that the information and attachments submitted with this closure report is true, accurate and complete to the best of my knowledge and belief. I also certify that the closure complies with all applicable closure requirements and conditions specified in the approved closure plan.

Name (Print): Jamie Goodwin	Title: Regulatory Tech.
Signature: Monce GoodWe	Date: 93014
e-mail address IGoodwin@logosoperating.com	Telephone: 505-330-9333

#### Logos Operating, LLC San Juan Basin Closure Report

#### Lease Name: LOGOS 8 API NO: 30-043-21156

In accordance with Rule 19.15.17.12 NMAC the following information describes the closure requirements of temporary pits on Logos Operating, LLC (Logos) locations. This is Logos' standard procedure for all temporary pits. A Separate plan will be submitted for any temporary pit that does not conform to this plan.

All closure activities will include proper documentation and be available for review upon request and will be submitted to OCD within 60 days of the pit closure. Closure report will be filed on C-144 and incorporated the following:

- Detail on Capping and Covering, where applicable (See report)
- Plot Plan (Pit diagram) (Included as an attachment)
- Inspection reports (Included as an attachment)
- Sampling Results (Included as an attachment)
- C-105 (Included as an attachment)
- Copy of Deed Notice will be filed with County Clerk (Not required on Federal, State or Tribal land as stated by FAQ dated October 30, 2008)

#### General Plan

1 All free standing liquids will be removed at the start of the pit closure process from the pit and disposed of in a division-approved facility or recycle, reuse or reclaim the liquids in a manner that the appropriate division district office approves.

All recovered liquids were disposed of at Basin Disposal (permit #NM-01-005) and any sludge or soil required to be removed to facilitate closure was hauled to Envirotech Land Farm (Permit #NM-01-011) and JFJ Landfarm % IEI (Permit #NM-01-0010B.

2 The preferred method of closure for all temporary pits will be on-site burial, assuming that all criteria listed in sub-section (D) of 19.15.17.13 are met.

#### The pit was closed using onsite burial.

3 The surface owner shall be notified of Logos proposed closure plan using a means that provides proof of notice i.e., certified mail, return receipt requested.

The closure process notification to the landowner was sent via certified mail. (See attached)

4 Within 6 months of the Rig Off status occurring Logos will ensure that temporary pits are closed, recontoured, and reseeded.

The closure plan requirements were met due to rig move off date as noted on C-105. (See attached). Pit closure extension to 4/22/14 was requested of the BIA per letter dated 1/13/14 and approved. Pit closure extension to 5/29/14 was requested of the BIA per letter dated 4/11/14 and approved.

- 5 Notice of Closure will be given to the Aztec Division office between 72 hours and one week of closure via email, or verbally, The notification of closure will include the following:
  - i. Operator's name
  - ii. Location by Unit Letter, Section, Township, and Range. Well name and API Number

#### Notification is attached.

6 Pit contents shall be mixed with non-waste containing, earthen material in order to achieve the solidification process. The solidification process will be accomplished using a combination of natural drying and mechanically mixing. Pit contents will be mixed with non-waste, earthen material to a consistency that is deemed a safe and stable. The mixing ratio shall not exceed 3 parts clean soil to 1 part pit contents.

Logos mixed the pit contents with non-waste containing, earthen material in order to achieve the solidification process. The solidification process was accomplished by using a combination of natural drying and mechanically mixing. Pit contents were mixed with non-waste, earthen material to a consistency that is deemed as safe and stable. The mixing ratio consisted of not more than 3 parts

clean soil to 1 part pit contents. Excess fill was hauled from Logos 8 pit to Logos 7 pit: ~260yds & to Logos 601H: ~80yds.

7 A five point composite sample will be taken of the pit using sampling tools and all samples tested per 19.15.17.13(D)(5). In the event that the criteria are not met, all contents will be handled per 9.15.17.13(D)(7) i.e., Dig and haul.

A five point composite sample was taken of the pit using sampling tools and all samples tested per 19.15.17.13(D)(5). (Sample results attached).

Components	Tests Method	Limit (mg/Kg)	Results (ppm)
Benzene	EPA SW-846 8021B or 8015M	10	SEE
BTEX	EPA SW-846 8021B or 8260B	50	ATTACHED
TPH	EPA SW-846 418.1	2500	
GRO/DRO	EPA SW-846 8015M	1000	
Chlorides	EPA 300.0	40000	

8 Upon completion of solidification and testing, Logos will fold the outer edges of the trench liner to overlap the waste material in the pit area, then install a geomembrane cover over the waste material in the pit to prevent collections of infiltration water after the soil cover is in place; geomembrane a 20-mil, string reinforced, LLDPE liner, or equivalent complying with EPA SW-846 method 9090A requirements.

# The pit material passed solidification and testing standards. Logos folded the outer edges of the trench liner to overlap the waste material in the pit area, then installed a geomembrane cover over the waste material and folded liner as per 19.15.17.13(8)(a)(b).

9 The pit area will be backfilled with compacted, non-waste containing, earthen material. A minimum of four feet of cover shall be achieved and the cover shall include one foot of suitable material to establish vegetation at the site, or the background thickness of topsoil, whichever is greater.

# The pit area was then backfilled with compacted, non-waste containing, earthen material. More than four feet of cover was achieved and the cover included one foot of suitable material to establish vegetation at the site.

10 Re-contouring of location will match fit, shape, line, form and texture of the surrounding area. Re-shaping will include drainage control, prevent ponding, and prevent erosion. Natural drainages will be unimpeded and water bars and/or silt traps will be placed in areas where needed to prevent erosion on a large scale. Final re-contour shall have a uniform appearance with smooth surface, fitting the natural landscape.

The pit area was re-contoured to match fit, shape, line, form and texture of the surrounding area. Reshaping included drainage control, to prevent ponding and erosion. Natural drainages were unimpeded and water bars and/or silt traps were placed in areas where needed to prevent erosion on a large scale. Final re-contour has a uniform appearance with smooth surface, fitting the natural landscape.

11 Notification will be sent to OCD when the reclaimed area is seeded.

# Provision 11 was accomplished in accordance with NMOCD 19.15.17.13(5)(d) Notification will be sent to the OCD when re-vegetation is established.

12 Logos shall seed the distributed areas the first growing season after the operator closes the pit. Seeding will be accomplished via drilling on the contour whenever practical or by other division-approved methods. BLM or Forest Service stipulated seed mixed will be used on federal lands. Vegetative cover will be established that will reflect a life-form ratio of plus or minus fifty percent (50%) of pre-disturbance levels and will equal seventy (70%) of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintain that cover thorough twp successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs.

Provision 12 was accomplished in accordance with NMOCD 19.15.17.13(5)(d) Notification will be sent to the OCD when re-vegetation is established.

13 The temporary pit will be located with a steel marker, no less than four inches in diameter, cemented in a hole three feet deep in the center of the onsite burial. The marker will be flush with the ground to allow access of the active well pad and for safety concerns. The marker will include a threaded collar to be used for future abandonment. The top of the marker will contain a welded steel 12" square plate that indicates the onsite burial of the temporary pit. The plate will be easily removable and a four foot tall riser will be threaded into the top of the collar marker and welded around the base with the operator's information at the time of all wells on the pad are abandoned. The operator's information will include the following: Operator Name, Lease Name. Well Name and number, Unit Number, Section, Township, Range and an indicator that the marker is an onsite burial location.

Provision 13 was accomplished by installing a steel marker in the temporary pit, no less than four inches in diameter, cemented in a hole three feet deep in the center of the onsite burial. The marker is flush with the ground to allow access of the active well pad and for safety concerns. The top of the marker contains a welded steel 12" square plate that indicates the onsite burial of the temporary pit. The plate contains the following: Operator's name, Lease Name, Well Name and number, Unit Number, Section, Township, Range and an indicator that the marker is an onsite burial location.

The plate will be easily removable and a four foot tall riser will be threaded into the top of the collar marker and welded around the base with the following operator's information at the time of all wells on the pad are abandoned. The riser will also indicate that the marker is for an onsite burial location.

Operator Name: LOGOS Lease Name & Well Number: LOGOS 8 Unit Letter: G Section: 5 Township: 22N Range: 05W API#: 30-043-21156 OBL

1

14 Logos inspected and documented daily and weekly reports on the above Temporary Pit. Logos inspected any liner breeches, fluid seeps or spills, HC's on top of temporary pit, free of miscellaneous solid waste or debris, discharge line integrity, fence integrity, any dead wildlife or livestock and inspection of the freeboard. Logos will provide maintained documentation of inspections upon request.

Inspection Start Date: 10/17/13 Inspection End Date: 5/13/14 NOTE: During start and end dates of temporary pit inspections no issues found.

# **Tamra Sessions**

From:	Tamra Sessions
Sent:	Monday, July 29, 2013 12:09 PM
То:	Merldine Oka (merldineoka@jicarillaoga.com)
Cc:	lsaac Julian (iajulian@yahoo.com); Kurt Sandoval (kurt.sandoval@bia.gov)
Subject:	SURFACE OWNER NOTIFICATION 07/29/13 - Temporary Pit
Attachments:	Jicarilla Pit Noitce.docx

Please see our attached notice for temporary pits on the following new drill locations:

Logos 7 Logos 8 Logos 9 Logos 10 Logos 11 Logos 12 Tamra Sessions Logos Resources, LLC

**Operations Technician** 

505-330-9333

1



4001 N. Butler Ave Farmington, NM 87401 Phone: (505) 436-2627 Fax: (505) 832-3095

Date: July 29, 2013

To: Jicarilla Apache Nation

Re: Surface Owner Notification for On-Site Burial

Ms. Merldine Oka Jicarilla Apache Nation Oil and Gas Administration #6 Dulce Rock Road Dulce, NM 87528

Re: Logos #7, Logos #8, Logos #9, Logos #10, Logos #11, and Logos #12

Dear Ms. Oka,

According to NMOCD rules, Logos Operating, LLC is notifying you that there will be temporary pits on the subject wells and that they intend to bury the drill cuttings in the reserve pit, assuming that they qualify as per Subsection D of 19.15.17.13 NMAC. No action is required on your part. If you have any questions, please do not hesitate to call me.

Regards,


Tamra Sessions

Tamra Sessions Operations Technician

!-	<u></u>											
	District I 1625 N. Frenc Phone:(575) 39	ch Drive. 93-5161	Hobbs, NM	1 88240	Fnerv		of New Mexi Natural Resource		lensetment		Revised	Form C-102 August 1, 2011
	District II 811 S. First	Street /	Artesia NM	88210		<i>y</i> , miner 613 G		.eg L		Appr	Subr opriate (	nit one copy to District Office
-	Phone:(5/5) /4 District III	48-1283	Fax: (575)	748-9720	0	IL CONSE	RVATION D	IVI	SION			
I	1000 Rio Braz Phone:(505) 33 District IV	205 H0a0, 34-6178	Aztec, NM Fax: (505)	87410 334-6170	1		St. Francis Fe, NM 875		rive		AMEND	ED REPORT
	1220 S. St. F Phone: (505) 47	rancis Dr 6-3460	rive, Santa Fax:(505)	Fe. NM 87 476-3462	7505	June	10, 141 070					
				WELL L	_OCATI	ON AND AC	REAGE DEDI	САТ	ION PLA	Т		
	'/	API Numbe	9F		*Pool Co	ode		wTI	'Pool Name LDCAT DA			
ł	*Property	Code				°Propert	y Name				* We	11 Number
	31196					LOG						8
	'OGRID N 28940					<sup>•</sup> Operator LOGOS RESO						levation 6888
L			<u> </u>		· · · · ·	<sup>10</sup> Surface						
	UL or lot no. G	Section	Township 22N	Range 5W	Lot Idn	Feet from the	North/South line NORTH		et from the 2250	East/We	st line	COUNTY SANDOVAL
L					n Hole		f Different					JANDOVAL
ſ	UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line		et from the	East/We	st line	County
┝	<sup>12</sup> Dedicated Acres	<u> </u>				<sup>13</sup> Joint or Infill	<sup>14</sup> Consolidation Code	<sup>15</sup> Orde	ar No.			
		40 a	cres SW	//4 NE/	4							
:	NO ALLOW	ABLE W	ILL BE A	ASSIGNED NON-ST	) TO TH ANDARD	IS COMPLETI UNIT HAS BE	ON UNTIL ALL	INT BY	ERESTS HA THE DIVIS	VE BE	EN CON	SOLIDATED
Γ	16			<u> </u>	30.00 '				" OPERA	TOR	CERTI	FICATION
	02		 					- 80	lknowlodoo an	d boliof	and that	mation contained the best of my this organization
	08. <i>LOT</i> 66. 4		L	.0T .3	Ω	LOT 2	LOT	35.1	mineral inter proposed boti	est in t tom-hole	he land in location o	or unleased cluding the r nas a right tion pursuant
	(Ľ) -				1640 <sup>-</sup>	-		1 <u>3</u> .	lito a contrac	t with an nterest. d	n owner or Ar to a vo	luntary poplang
					11.5.6				heretofore er	tered by	the divis	5/2/13
		1					2250'		Signaturo	t.	Gral	
	00.02E1	ĺ				: 36.16916 N		- 00	Printed Name		0	son cedleres
					DA	5: 107.38270 *W TUM: NAD1927 7: 36.16917 *N		320.0	E-mail Addre	255	J	
		1			LONG	: 107.38330 W TUM: NAD1983		Ω	I hereby ce shown on th	YUH L Prtify that will be a constructed by the second s	LENIIA at the well was plotter	ICATION l location d from field by me or under ame is true
			<u> </u>		5		<u> </u>	-	notes of ac my supervis and correct	tual surv ion, and to to the b	reys made t that the s best of my	by me or under ame is true belief.
ŀ		í								und Cool o	of Doofore	H 14, 2013
										~ 0	C. Enu	
.	_	ĺ					1		· /·	JASON C	MEXICO	B.
		·	• · · · · · · · · · · · · · · · · ·		_	- <u></u>		0.00	/a		$\sim 20$	<b>N N I</b>
	Л О 4						1 # 4	2640	GIS	( /	$\mathcal{I}$	R HELOH
										AD AROF	ESSIONAL	3
		}										
							 		UASON Certif	icate N	iumber	DWARDS 15269

5277.36

\_ \_ \_



## Table 1, Summary of Analytical Results Logos Operating, LLC Logos #8 Drill Pit Closure and Backfill Material Sampling Report Sandoval County, New Mexico Project Number 12035-0038

Sample Description	Sample Number	Date	TPH USEPA Method 418.1 (ppm)	TPH USEPA Method 8015 (ppm)	Benzene USEPA Method 8021 (ppm)	BTEX USEPA Method 8021 (ppm)	Chlorides USEPA Method 300.0 (ppm)
NMOCD/RCRA Standards	NA	NA	2500	1000	10	50	40000
Drill Pit Composite	1	1/17/2014	36100	8403	ND	2.12	188
Logos #8	1	3/31/2014	1500	174	NS	NS	NS
NMOCD/RCRA Standards	NA	NA	NA	NA	NA	NA	600
West Backfill Material Composite	1	1/23/2014	NS	NS	NS	NS	ND
East Backfill Material Composite	2	1/23/2014	NS	NS	NS	NS	ND

:

NS = Not Sampled

ND = Non-Detect at Stated Method's Detection Limit

\* Values in **BOLD** above regulatory standards



# **Analytical Report**

## **Report Summary**

Client: Logos Operating, LLC Chain Of Custody Number: 16522 Samples Received: 1/17/2014 4:30:00PM Job Number: 12035-0038 Work Order: P401045 Project Name/Location: Logos #8

Date: 1/23/14

Entire Report Reviewed By:

Tim Cain, Laboratory Manager

The results in this report apply to the samples submitted to Envirotech's Analytical Laboratory and were analyzed in accordance with the chain of custody document supplied by you, the client, and as such are for your exclusive use only. The results in this report are based on the sample as received unless otherwise noted. Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc. If you have any questions regarding this analytical report, please don't hesitate to contact Envirotech's Laboratory Staff.

Three Springs • 65 Mercado Street, Suite 115, Durango, CO 81301

Ph (505) 632-0615 Fx (505) 632-1865 Ph (970) 259-0615 Fr (800) 362-1879





	Logos Operating, LLC	Project Name:	Logos #8		
	PO Box 18	Project Number:	12035-0038	Reported:	
1	Flora Vista NM, 87415	Project Manager:	Tiffany McIntosh	23-Jan-14 09:53	1

## **Analyical Report for Samples**

Client Sample ID	Lab Sample ID	Matrix	Sampled	Received	Container
Drill Pit Composite	P401045-01A	Sludge	01/17/14	01/17/14	Glass Jar, 4 oz.

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

5796 US Highway 64, Farmington, NM 87401

Three Springs • 65 Mercado Street, Suite 115, Durango, CO 81301

Ph (505) 632-0615 Fx (505) 632-1865 Ph (970) 259-0615 Fr (800) 362-1879



Page 2 of 10



Logos Operating, LLC PO Box 18 Flora Vista NM, 87415	Projec	et Name: et Number: et Manager:		os #8 5-0038 ny McIntosh	1			<b>Reported:</b> 23-Jan-14 09	
			it Comp 45-01 (Sc						
1 			45 01 (50	,iid)					
Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
Volatile Organize by EBA 9021						-		· · · · · · · · · · · · · · · · · · ·	
Volatile Organics by EPA 8021 Benzene	ND	0.05	mg/kg	<u> </u>	1404001	01/20/14	01/20/14	EPA 8021B	
Toluene	0.05	0.05	mg/kg	1	1404001	01/20/14	01/20/14	EPA 8021B	
Ethylbenzene	0.10	0.05	mg/kg	1	1404001	01/20/14	01/20/14	EPA 8021B	
p,m-Xylene	1.88	0.05	mg/kg	1	1404001	01/20/14	01/20/14	EPA 8021B	
o-Xylene	0.09	0.05	mg/kg	1	1404001	01/20/14	01/20/14	EPA 8021B	
Total Xylenes	1.97	0.05	mg/kg	1	1404001	01/20/14	01/20/14	EPA 8021B	
Total BTEX	2.12	0.05	mg/kg	1	1404001	01/20/14	01/20/14	EPA 8021B	
Surrogate: Bromochlorobenzene		118 %	80-	-120	1404001	01/20/14	01/20/14	EPA 8021B	
Surrogate: 1,3-Dichlorobenzene		113 %	80-	120	1404001	01/20/14	01/20/14	EPA 8021B	
Nonhalogenated Organics by 8015									
Gasoline Range Organics (C6-C10)	72.7	4.98	mg/kg	1	1404001	01/20/14	01/20/14	EPA 8015D	
Diesel Range Organics (C10-C28)	8330	29.9	mg/kg	1	1404002	01/20/14	01/20/14	EPA 8015D	
				•					
Total Petroleum Hydrocarbons by 418.1	26100	200	malka	10	1404003	01/20/14	01/20/14	EPA 418.1	
Total Petroleum Hydrocarbons	36100	200	mg/kg	10	1404003	01/20/14	01/20/14	EFA 410.1	
Cation/Anion Analysis									
Chloride	188	9.95	mg/kg	1	1404016	01/22/14	01/22/14	EPA 300.0	

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

5796 US Highway 64, Farmington, NM 87401

Three Springs - 65 Mercado Street, Suite 115, Durango, CO 81301

envirotech inc.com Haboratory een virotech inc.com

Page 3 of 10



Logos Operating, LLC	Project Name:	Logos #8		
PO Box 18	Project Number:	12035-0038	Reported:	
Flora Vista NM, 87415	Project Manager:	Tiffany McIntosh	23-Jan-14 09:53	

#### Volatile Organics by EPA 8021 - Quality Control

#### **Envirotech Analytical Laboratory**

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 1404001 - Purge and Trap EPA 5030/	<u> </u>									
Blank (1404001-BLK1)				Prepared: 2	20-Jan-14 A	Analyzed: 2	I-Jan-14			
Benzene	ND	0.05	mg/kg					·		
Toluene	ND	0.05								
Ethylbenzene	ND	0.05								
p.m-Xylene	ND	0.05	*1							
o-Xylene	ND	0.05	"							
Total Xylenes	ND	0.05	"							
Total BTEX	ND	0.05	"							
Surrogate: 1,3-Dichlorobenzene	45.7		ug/L	50.0		91.5	80-120			
Surrogate: Bromochlorobenzene	46.7		"	50.0		93.5	80-120			
Duplicate (1404001-DUP1)	Sou	rce: P401044-	01	Prepared &	Analyzed:	20-Jan-14				
Benzene	ND	0.05	mg/kg		ND				30	
Toluene	ND	0.05	н		ND				30	
Ethylbenzene	ND	0.05	"		ND				30	
p.m-Xylene	ND	0.05			ND				30	
o-Xylene	ND	0.05	"		ND				30	
Surrogate: 1,3-Dichlorobenzene	46.6	······	ug/L	50.0		93.3	80-120			
Surrogate: Bromochlorobenzene	47.8		"	50.0		95.6	80-120			
Matrix Spike (1404001-MS1)	Sou	rce: P401044-	01	Prepared &	Analyzed:	20-Jan-14				
Benzene	50.3		ug/L	50.0	ND	101	39-150			
Foluene	50.1			50.0	ND	100	46-148			
Ethylbenzene	50.3		"	50.0	ND	101	32-160			
,m-Xylene	100		"	100	ND	100	46-148			
-Xylene	49.7		"	50.0	ND	99.3	46-148	_		
Surrogate: 1,3-Dichlorobenzene	50.8		"	50.0		102	80-120			
Surrogate: Bromochlorobenzene	50.1		"	50.0		100	80-120			

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

5796 US Highway 64, Farmington, NM 87401

Three Springs • 65 Mercado Street, Suite 115, Durango, CO 81301

ALC: NO	envirotecn=incicom)*	
1. 6.00		
Slabora	ory@envirotech.inc.com	

Page 4 of 10



Logos Operating, LLC	Proj	ect Name:	L	ogos #8						
PO Box 18	Ргој	ect Number:	1	2035-0038					Report	ed:
Flora Vista NM, 87415	Proj	ect Manager:	Т	iffany McInto	osh				23-Jan-14	09:53
	Nonhaloge	enated Org	anics by	y 8015 - Qi	uality Co	ntrol				
Envirotech Analytical Laboratory										
	· ···	Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
Batch 1404001 - Purge and Trap EP	A 5030A		· 			· · ·	· 		M	
Blank (1404001-BLK1)				Prepared: 2	20-Jan-14 A	Analyzed: 2	1-Jan-14			
Gasoline Range Organics (C6-C10)	ND	4.99	mg/kg							
Duplicate (1404001-DUP1)	Sour	ce: P401044-	01	Prepared &	Analyzed:	20-Jan-14				
Basoline Range Organics (C6-C10)	ND	5.00	mg/kg		ND				30	
Aatrix Spike (1404001-MS1)	Sour	ce: P401044-	01	Prepared &	Analyzed:	20-Jan-14				
Gasoline Range Organics (C6-C10)	0.49		mg/L	0.450	0.02	106	75-125			

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

5796 US Highway 64, Farmington, NM 87401

Three Springs - 65 Mercado Street, Suite 115, Durango, CO 81301

Ph (505) 632-0615 Fx (505) 632-1865 Ph (970) 259-0615 Fr (800) 362-1879

Page 5 of 10



Logos Operating, LLC	Projec	t Name:	L	ogos #8						
PO Box 18	Projec	t Number:	1	2035-0038					Report	ted:
Flora Vista NM, 87415	Projec	t Manager:	Т	iffany McInto	sh				23-Jan-14	09:53
1 	Nonhalogen	ated Org	anics by	y 8015 - Qi	ality Co	ntrol				
Envirotech Analytical Laboratory										
1		Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
	A 3550C			Prepared &	Analyzed:	20-Jan-14				
3lank (1404002-BLK1)	ND	30.0	mg/kg	Prepared &	Analyzed:	20-Jan-14				
Blank (1404002-BLK1) Diesel Range Organics (C10-C28)	ND .	30.0 <b>: P401044-(</b>		Prepared & Prepared &						
Blank (1404002-BLK1) Diesel Range Organics (C10-C28) Duplicate (1404002-DUP1)	ND .			*				46.2	30	DI
Batch 1404002 - DRO Extraction EF Bla <sup>i</sup> nk (1404002-BLK1) Diesel Range Organics (C10-C28) Duplicate (1404002-DUP1) Diesel Range Organics (C10-C28) Matrix Spike (1404002-MS1)	ND <b>Source</b> 126	: P401044-(	)1 mg/kg	*	Analyzed: 202	20-Jan-14		46.2	30	Dl

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

5796 US Highway 64, Farmington, NM 87401

÷

Ph (505) 632-0615 Fx (505) 632-1865

Three Springs - 65 Mercado Street, Suite 115, Durango, CO 81301

	100
envirotech-inc.com	
Elaboratory@envirotech-inc.com	遷
	<b>2</b>

Page 6 of 10



Logos Operating, LLC	Project Name:	Logos #8	
PO Box 18	Project Number:	12035-0038	Reported:
Flora Vista NM, 87415	Project Manager:	Tiffany McIntosh	23-Jan-14 09:53

#### Total Petroleum Hydrocarbons by 418.1 - Quality Control

### **Envirotech Analytical Laboratory**

1			•		-					
Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 1404003 - 418 Freon Extraction										
Blank (1404003-BLK1)				Prepared &	Analyzed:	20-Jan-14				
Total Petroleum Hydrocarbons	ND	20.0	mg/kg							
Duplicate (1404003-DUP1)	Sourc	e: P401044-	01	Prepared &	Analyzed:	20-Jan-14				
Total Petroleum Hydrocarbons	84.0	20.0	mg/kg		99.7			17.1	30	
				<b>D</b> 10		<b>.</b>				
Matrix Spike (1404003-MS1)	Sourc	e: P401044-	-01	Prepared &	Analyzed:	20-Jan-14				
Total Petroleum Hydrocarbons	627		mg/L	500	25.0	120	80-120			

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

5796 US Highway 64, Farmington, NM 87401

Three Springs - 65 Mercado Street, Suite 115, Durango, CO 81301



	Logos Operating, LLC	Project Name: Logos #8	
ł	PO Box 18	Project Number: 12035-0038	Reported:
	Flora Vista NM, 87415	Project Manager: Tiffany McInto	sh 23-Jan-14 09:53

## **Cation/Anion Analysis - Quality Control**

## **Envirotech Analytical Laboratory**

	<b>D</b> 1	Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
Batch 1404016 - Anion Extraction EPA	300.0									
Blank (1404016-BLK1)				Prepared &	Analyzed:	22-Jan-14				
Chloride	ND	9.92	mg/kg							
LCS (1404016-BS1)				Prepared &	Analyzed:	22-Jan-14				
Chloride	529	9.97	mg/kg	499		106	90-110			
Matrix Spike (1404016-MS1)	Source	e: P401058-	01	Prepared &	Analyzed:	22-Jan-14				
Chloride	503	9.98	mg/kg	499	12.2	98.4	80-120			
Matrix Spike Dup (1404016-MSD1)	Source	e: P401058-	01	Prepared &	Analyzed:	22-Jan-14				
Chloride	501	9.89	mg/kg	495	12.2	98.8	80-120	0.506	20	

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

5796 US Highway 64, Farmington, NM 87401

Three Springs - 65 Mercado Street, Suite 115, Durango, CO 81301

Ph (970) 259-0615 Fr (800) 362-1879



PO Box	perating, LLC 18 sta NM, 87415	Project Name: Project Number: Project Manager:	Logos #8 12035-0038 Tiffany McIntosh	<b>Reported:</b> 23-Jan-14 09:53
		Notes and I	Definitions	1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 - 1999 -
PK1	The spike recovery for this QC s	cample is outside of control limits.		
)Ì	Duplicates or Matrix Spike Dup	licates Relative Percent Difference ex	cceeds 30%.	
ËT	Analyte DETECTED			
Ď	Analyte NOT DETECTED at or abo	ve the reporting limit		
R	Not Reported			
y	Sample results reported on a dry we	ght basis		
Ρ̈́D	Relative Percent Difference			
4				
I				
1 4				
	Partial or incomp	lete reproduction of this report	is prohibited, unless approved by E	nvirotech, Inc.
	nhway 64 Farmington, NM 87401		) 632-0615 Fx (505) 632-1865	envirotechiinGcom)

5796 US Highway 64, Farmington, NM 87401

Three Springs • 65 Mercado Street, Suite 115, Durango, CO 81301

Page 9 of 10

16522

# CHAIN OF CUSTODY RECORD

Client: LOCIOS OPEVA Email résults to:	tina	Pr	Diject Name / Location	on: ± 8				ANALYSIS / PARAMETERS													
Email results to: T, MCIntos Client Phone No.: 505 - 330 -	h		Logos Ħ Impler Name: T. MCIV ent No.: 12035	tosh	3			TPH (Method 8015)	BTEX (Method 8021)	VOC (Method 8260)	RCRA 8 Metals	Cation / Anion		TCLP with H/P	CO Table 910-1	118.1)	RIDE			Sample Cool	Sample Intact
Sample No./ Identification	Sample Date	Sample Time	Lab No.	No./Volume of Containers	Pr HNO3	eservati нсі	ve Cool	ТРН (Л	втех	voc (I	RCRA	Cation	RCI	TCLP	CO Tal	TPH (418.1)	CHLORIDE			Sampl	Sampl
Drill Pit Composite	1/17/14	315	P401045-01	1-4 <i>oz j</i> 'ar			×	×	X							X	×			<u>}</u>	<u> </u>
		- 																			
Relinquished by: (Signature)	USA	itos	N	1/17/14/630		ived t						/		-					Da 177		Time 1430
Sample Matrix Soil 🗋 Solid 🗋 Sludge 🗹		] Other [	]																		
Sample(s) dropped off after	hours to se	cure drop	off area.	3 env								13	. 50	Έ							
5795 US Highway 64	4 • Farmingt	on, NM 874	01 • 505-632-0615 •	Three Springs • 65 M	Aerco	ido Str	reet, S	Suite	115, C	Duran	go, (	0 81	301 •	labo	orato	ry@ēi	nvirot		Pa		0 of 10



# **Analytical Report**

## **Report Summary**

Client: Logos Operating, LLC Chain Of Custody Number: 16555 Samples Received: 1/23/2014 3:10:00PM Job Number: 12035-0038 Work Order: P401068 Project Name/Location: Logos #8

Date: 1/27/14

Entire Report Reviewed By:

Tim Cain, Laboratory Manager

The results in this report apply to the samples submitted to Envirotech's Analytical Laboratory and were analyzed in accordance with the chain of custody document supplied by you, the client, and as such are for your exclusive use only. The results in this report are based on the sample as received unless otherwise noted. Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc. If you have any questions regarding this analytical report, please don't hesitate to contact Envirotech's Laboratory Staff.

Three Springs • 65 Mercado Street, Suite 115, Durango, CO 81301

Ph (505) 632-0615 Fx (505) 632-1865 Ph (970) 259-0615 Fr (800) 362-1879 envirotech-inc.com laboratory@envirotech-inc.com

Page 1 of 7



Logos Operating, LLC	Project Name:	Logos #8		
PO Box 18	Project Number:	12035-0038	Reported:	
Flora Vista NM, 87415	Project Manager:	Tiffany McIntosh	27-Jan-14 08:35	

# **Analyical Report for Samples**

Client Sample ID	Lab Sample ID	Matrix	Sampled	Received	Container
West Backfill Material Composite	P401068-01A	Soil	01/23/14	01/23/14	Glass Jar, 4 oz.
East Backfill Material Composite	P401068-02A	Soil	01/23/14	01/23/14	Glass Jar, 4 oz.

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

5796 US Highway 64, Farmington, NM 87401	Ph (505) 632-0615	Fx (505) 632-1865	envirotech-inc.com
Three Springs - 65 Mercado Street, Suite 115, Durango, CO 81301	Ph (970) 259-0615	Fr (800) 362-1879	: laboratory@envirotech-inc.com

Page 2 of 7



Logos Operating, LLC	Project Name:	Logos #8	
PO Box 18	Project Number:	12035-0038	Reported:
Flora Vista NM, 87415	Project Manager:	Tiffany McIntosh	27-Jan-14 08:35

#### West Backfill Material Composite

P401068-01 (Solid)										
Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes	
Cation/Anion Analysis Chloride	ND	9.87	mg/kg	1	1404028	01/24/14	01/24/14	EPA 300.0	<u></u>	

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

 5796 US Highway 64, Farmington, NM 87401
 Ph (505) 632-0615
 Fx (505) 632-1865
 enviroiech-inc.com

 Three Springs • 65 Mercado Street, Suite 115, Durango, CO 81301
 Ph (970) 259-0615
 Fr (800) 362-1879
 Laboratory@enviroiech-inc.com

Page 3 of 7

envirotech Analytical Laboratory

Logos Operating, LLC PO Box 18 Flora Vista NM, 87415		Name: Number: Manager:	1203	os #8 35-0038 any McIntosł	1			<b>Reported:</b> 27-Jan-14 08	
	Eas			l Compos	ite				
	<u>,</u>		068-02 (S	olid)	<u></u>			<u></u>	
Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
ation/Anion Analysis									
hloride	ND	9.99	mg/kg	1	1404028	01/24/14	01/24/14	EPA 300.0	
				•					
Partial or inc	complete reproduction of	this repo	rt is proh	ibited, unle	ess appro	ved by Envi	rotech, Inc.		

5796 US Highway 64, Farmington, NM 87401

Three Springs • 65 Mercado Street, Suite 115, Durango, CO 81301

Ph (505) 632-0615 Fx (505) 632-1865 Ph (970) 259-0615 Fr (800) 362-1879



Page 4 of 7



I

1

Logos Operating, LLC	Project Name:	Logos #8	
PO Box 18	Project Number:	12035-0038	Reported:
Flora Vista NM, 87415	Project Manager:	Tiffany McIntosh	27-Jan-14 08:35

### **Cation/Anion Analysis - Quality Control**

### **Envirotech Analytical Laboratory**

1										
		Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
Batch 1404028 - Anion Extraction EPA 300.0		•								
Blank (1404028-BLK1)				Prepared &	Analyzed:	24-Jan-14				
Çhloride	ND	9.94	mg/kg							
LCS (1404028-BS1)				Prepared &	Analyzed:	24-Jan-14				
Chloride	498	9.97	mg/kg	499		99.9	90-110			
Matrix Spike (1404028-MS1)	Sour	ce: P401067-	01	Prepared &	Analyzed:	24-Jan-14				
Chloride	545	9.95	mg/kg	498	ND	110	80-120			
Matrix Spike Dup (1404028-MSD1)	Sour	ce: P401067-	01	Prepared &	Analyzed:	24-Jan-14				
Chloride	553	9.96	mg/kg	498	ND	111	80-120	1.48	20	

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

5796 US Highway 64, Farmington, NM 87401	Ph (505) 632-0615	Fx (505) 632-1865	envirotech-inc.com
Three Springs • 65 Mercado Street, Suite 115, Durango, CO 81301	Ph (970) 259-0615	Fr (800) 362-1879	, laboratory@envirotech-incicom;

Page 5 of 7



PO Box 18	erating, LLC 3 a NM, 87415	Project Name: Project Number: Project Manager:	Logos #8 12035-0038 Tiffany McIntosh	<b>Reported:</b> 27-Jan-14 08:35
 		Notes and De	finitions	
DET	Analyte DETECTED			
ND	Analyte NOT DETECTED at or above the reporting	g limit		
NR	Not Reported			
dry	Sample results reported on a dry weight basis			
RPD	Relative Percent Difference			
i				

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

 5796 US Highway 64, Farmington, NM 87401
 Ph (505) 632-0615
 Fx (505) 632-1865
 envirotech-inc.com

 Three Springs - 65 Mercado Street, Suite 115, Durango, CO 81301
 Ph (970) 259-0615
 Fr (800) 362-1879
 Iaboratory@envirotech-inc.com

Page 6 of 7

# CHAIN OF CUSTODY RECORD

16555

	Client: Logos Oper	ratina	Pro	Dject Name / Locatio					ANALYSIS / PARAMETERS													
	Email results to: T. McIntosh	mpler Name: Ti Mc Int					8015) d 8021)	d 8021)	8260)	<u>s</u>				<del>.</del>								
	Client Phone No.: 505-320-2	857		ent No.:  2035 - 00	38		TPH (Method 8015)	BTEX (Method 8021)	VOC (Method 8260)	RCRA 8 Metals	Cation / Anion		TCLP with H/P	CO Table 910-1	TPH (418.1)	RIDE			Sample Cool	Sample Intact		
	Sample No./ Identification	Sample Date	Sample Time	Lab No.	No./Volume of Containers	Pr HNO3	eservat HCI	ive Cool	ТРН (I	втех	voc (	RCRA	Cation	RCI	TCLP	CO Ta	трн (	CHLORIDE			Samo	Sampl
IES	composite	1/23/14	9:48	P401068-01	1-40zjar	1		X										Х			Y	11
	East backfill material composite		9:44	P401068-02				1													Y	<u>{                                    </u>
	· · · · · · · · · · · · · · · · · · ·																				+-	+
	· · · · · · · · · · · · · · · · · · ·					-																
																					+	
		<u> </u>																<b> </b>				+
	······································																 				-	
	Relinquished by: (Signature)	Mr. D.	tal		Date Time	Rece	ived t	by: (S	ignat	iure)				-	<b>I</b>	L	I	L	Ă	Da		Time
	Relinquished by: (Signature)	IVDAN	MM	/	1/23/14 1510	Rece	ived l	oy: (S	ignat	ture)		ŀ	m	_						/21	14	1510
	Sample Matrix Soll 🖸 Solid 🗋 Sludge 🗋	Aqueous [	] Other [	]									r							-		
	Sample(s) dropped off after	hours to se	cure drop o	off area.	3 env	ir ( lytic	ot al La	ee		<b>)</b>		1_2	+ ~	$\langle$	1	].	3			<u></u>	1	
	5795 US Highway 6	4 • Farmingt	on, NM 874	01 • 505-632-0615 • 7														virote	ech-inc	P	age	7 of 7



# **Analytical Report**

## **Report Summary**

Client: Logos Operating, LLC Chain Of Custody Number: 16795 Samples Received: 3/31/2014 4:06:00PM Job Number: 12035-0038 Work Order: P404001 Project Name/Location: Logos #8

Date: 4/4/14

Entire Report Reviewed By:

Tim Cain, Laboratory Manager

The results in this report apply to the samples submitted to Envirotech's Analytical Laboratory and were analyzed in accordance with the chain of custody document supplied by you, the client, and as such are for your exclusive use only. The results in this report are based on the sample as received unless otherwise noted. Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc. If you have any questions regarding this analytical report, please don't hesitate to contact Envirotech's Laboratory Staff.

Three Springs - 65 Mercado Street, Suite 115, Durango, CO 81301

Ph (505) 632-0615 Fx (505) 632-1865 Ph (970) 259-0615 Fr (800) 362-1879



Page 1 of 7

Logos Operating, LLC	Project Name:	Logos #8	
PO Box 18	Project Number:	12035-0038	Reported:
, Flora Vista NM, 87415	Project Manager:	Eric Liese	04-Apr-14 16:42

## **Analyical Report for Samples**

Client Sample ID	Lab Sample ID	Matrix	Sampled	Received	Container
Drill Pit	P404001-01A	Soil	03/31/14	03/31/14	Glass Jar, 4 oz.
·					

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

5796 US Highway 64, Farmington, NM 87401	Ph (505) 632-0615 Fx (505) 632-1865	enviroledi inciom diboratory genvirolech inciom
Three Springs • 65 Mercado Street, Suite 115, Durango, CO 81301	Ph (970) 259-0615 Fr (800) 362-1879	Claboratory@envirotech*indcom?



Logos Operating, LLC PO Box 18 Flora Vista NM, 87415	Projec	et Name: et Number: et Manager:	1203	os #8 35-0038 Liese				<b>Reported:</b> 04-Apr-14 16	
			Drill Pit 01-01 (Sc	olid)					
Analyte	Result	Reporting Limit	Units	Dilution	Batch	Prepared	Analyzed	Method	Notes
Nonhalogenated Organics by 8015									
Gasoline Range Organics (C6-C10)	ND	4.99	mg/kg	1	1414025	04/02/14	04/04/14	EPA 8015D	
Diesel Range Organics (C10-C28)	173	30.0	mg/kg	1	1414024	04/02/14	04/04/14	EPA 8015D	

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

5796 US Highway 64, Farmington, NM 87401	Ph (505) 632-0615	Fx (505) 632-1865	- serviroischime.com Aliboistory serviroisch anc.com
Three Springs - 6S Mercado Street, Suite 115, Durango, CO 81301	Ph (970) 259-0615	Fr (800) 362-1879	alaboratory@envirotech_inecom(s

Page 3 of 7

# envirotech Analytical Laboratory

	Logos Operating, LLC	Project Name:	Logos #8	c l
1	PO Box 18	Project Number:	12035-0038	Reported:
	Flora Vista NM, 87415	Project Manager:	Eric Liese	04-Apr-14 16:42

#### Nonhalogenated Organics by 8015 - Quality Control

## **Envirotech Analytical Laboratory**

			•		•					
Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 1414024 - DRO Extraction EPA 3550C										
Blank (1414024-BLK1)				Prepared: (	02-Apr-14	Analyzed: (	04-Apr-14			
Diesel Range Organics (C10-C28)	ND	30.0	mg/kg							
Duplicate (1414024-DUP1)	Sour	ce: P404001-	01	Prepared: (	02-Apr-14	Analyzed: (	)4-Apr-14			
Diesel Range Organics (C10-C28)	322	29.9	mg/kg		173			60.4	30	DI
Matrix Spike (1414024-MS1)	Sour	ce: P404001-	01	Prepared: (	)2-Apr-14	Analyzed: (	)4-Apr-14			
Diesel Range Organics (C10-C28)	683	29.9	mg/kg	49.8	173	NR	75-125			SPK1

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

 5796 US Highway 64, Farmington, NM 87401
 Ph (505) 632-0615
 Fx (505) 632-1865
 Cenviroled a finacion

 Three Springs - 65 Mercado Street, Suite 115, Durango, CO 81301
 Ph (970) 259-0615
 Fr (800) 362-1879
 IEborator / cenviroled a finacion

Page 4 of 7



Logos Operating, LLC	Project Name:	Logos #8	
PO Box 18	Project Number:	12035-0038	Reported:
Flora Vista NM, 87415	Project Manager:	Eric Liese	04-Apr-14 16:42

#### Nonhalogenated Organics by 8015 - Quality Control

Envirotech Analytical Laboratory										
Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch 1414025 - Purge and Trap EPA 5030A										
Blank (1414025-BLK1)				Prepared: (	02-Apr-14	Analyzed: (	04-Apr-14			
Gasoline Range Organics (C6-C10)	ND	4.99	mg/kg							
Duplicate (1414025-DUP1)	Sou	rce: P404001-	-01	Prepared: 0	)2-Apr-14	Analyzed: (	04-Apr-14			
Gasoline Range Organics (C6-C10)	ND	4.99	mg/kg		ND				30	
Matrix Spike (1414025-MS1)	Sou	rce: P404001-	-01	Prepared: 0	)2-Apr-14	Analyzed: (	04-Apr-14			
Gasoline Range Organics (C6-C10)	0.63		mg/L	0.450	0.03	132	75-125			SPK1

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

5796 US Highway 64, Farmington, NM 87401	Ph (505) 632-0615 Fx (505) 632-1865	, envirotech, inc.com Eboratory@envirotech-inc.com
Three Springs • 65 Mercado Street, Suite 115, Durango, CO 81301	Ph (970) 259-0615 Fr (800) 362-1879	alaboratory.genviro(ech-inecom)

Page 5 of 7



PO Box	berating, LLC 8 ta NM, 87415	Project Name: Project Number: Project Manager:	Logos #8 12035-0038 Eric Liese	Reported: 04-Apr-14 16:42
		Notes and I	Definitions	
SPKI	The spike recovery for this QC sample is o	utside of control limits.		
DI	Duplicates or Matrix Spike Duplicates Rela	ative Percent Difference ex	ceeds control limits.	
DET	Analyte DETECTED			
ND	Analyte NOT DETECTED at or above the report	ting limit		
NR	Not Reported			
dry	Sample results reported on a dry weight basis			
RPD	Relative Percent Difference			

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

5796 US Highway 64, Farmington, NM 87401	Ph (505) 632-0615	envirotech-inc.com Ibboratory@envirotech-inc.com
Three Springs • 65 Mercado Street, Suite 115, Durango, CO 81301	Ph (970) 259-0615 Fr (800) 362-1879	laboratory@envirotech-inc.com

Page 6 of 7

## CHAIN OF CUSTODY RECORD

16795

Client:	27710	Pro	ject Name / Locatio		16919	5 9							A	NALY	SIS .	/ Paf	RAME	TER	S			
Email results to: Enc. Environ Client Phone No.:	ment	Sar Clie	iect Name / Location where the second secon	<i>Σι</i> ε - α	1.50, )38				TPH (Method 8015)	BTEX (Method 8021)	VOC (Method 8260)	RCRA 8 Metals	Cation / Anion		TCLP with H/P	CO Table 910-1	418.1)	RIDE			Samla Cool	Sample Intact
Sample No./ Identification	Sample Date	Sample Time	Lab No.		Volume ontainers	Pr HNO3	eservat нсі	tive Cool	TPH (N	втех	voc (	RCRA	Cation	RCI	TCLP	со та	TPH (418.1)	CHLORIDE			Camol	Sampl
1000 # 8-	3-31-14	1130	P404001-01	1	loz			Х	Х													- 🗸
Doill Pir			·																			
					<u> </u>										 						+	
																					+-	-
		· · · · · ·																			+	
					<u>.</u>		ļ	[														
Relinquished by: (Signature)	$\geq$			Date	Time 1605	Rece	ived I	by: (S	ignat	ure)	 - /V		<u>_</u>			.		<u> </u>		Di 331	ite 14:	Time
Relinquished by: (Signature)		<b>`</b> .				Rece	ived	by: (€	Ignat	ure)			_						<u> </u>			
Sample Matrix Soll 🔲 Solid 🗀 Sludge 🔀	Aqueous [	] Other []]																				
Sample(s) dropped off after	r hours to se	cure drop of	E		env							5.0					-			<b>-</b>	1	
5795 US Highway 8	4 • Farming	ton, NM 8740	01 • 505-632-0615 •	Three Sp	prings • 65 M	Merca	do St	reet,	Suite	115, 0	Durar	go, (	CO 81	301 •	labo	orator	y@ei	nvirote	ech-in	C F	age	7 of 7

Submit To Appropria Two Copies	ate District	Office				State of Ne	ew N	1exi	co							Fc	rm C-105		
District I 1625 N. French Dr.,	Hobbs, NN	A 88240		Ene	ergy,	Minerals and	d Na	tura	l Re	sources		1. WELL		NO	Re	evised A	ugust 1, 2011		
District II 811.S. First St., Arter	sia, NM 88	3210			Oi	l Conservat	tion	Div	icia	\n		30-043-211	156	NO.					
District III 1000 Rio Brazos Rd.	, Aztec, NI	M 87410				20 South S						2. Type of Lo		☐ FE		FED/IND			
District IV 1220 S. St. Francis D	Dr., Santa F	e, NM 8750	5			Santa Fe, N						3. State Oil &	k Gas	Lease N	0.				
WELL C	OMPL	ETION		RECC	MPL	ETION RE	POF			LOG		JICARILLA	<u>APAC</u>	HE LEA	ASE #424		the state of the s		
4. Reason for filin												<ul> <li>5. Lease Name or Unit Agreement Name LOGOS</li> </ul>							
COMPLETIC	ON REPC	<b>DRT</b> (Fill	n boxes	#1 throu	gh #31	for State and Fee	e wells	s only]	)			6. Well Numb	ber: 8			- 11 - 5			
C-144 CLOSU #33; attach this and	the plat	TACHME to the C-1	NT (Fil 44 closu	l in boxe re report	s #1 thr	ough #9, #15 Da rdance with 19.1	ate Rig 5.17.1	g Rele: 3.K N	ased MA	and #32 and C)	l/or								
	ELL 🔲	WORKO	VER	] DEEPE	ENING	PLUGBACH	K 🗖	DIFFI	EREI	NT RESERV	VOIF	R OTHER				_			
8. Name of Operator LOGOS OPERATING, LLC									9. OGRID 289408										
10. Address of Ope 4001 North Butler	erator		101 Ear	nington	NIN / 97	401						11. Pool name	or W	ildcat					
															- 1				
12.Location	Jnit Ltr	Sectio	n	Towns	hip	Range	Lot			Feet from	the	N/S Line	Feet	from th	e E/W	Line	County		
BH:		-		-	· · · ·														
13. Date Spudded	14. Dat	e T.D. Re	ached			Released	L		16.	Date Comp	letec	I I (Ready to Prod	Luce)				and RKB,		
18. Total Measured	Depth of	f Well		10/18 19. P		k Measured Dep	oth		20.	Was Direc	tiona	RT, GR, etc.) al Survey Made? 21. Type Electric and Other			her Logs Run				
22. Producing Inter	•		letion - '		-	•													
		·			<u> </u>		0.01			. 11 .			11)						
23. CASING SIZI	E	WEIG	HT LB./			ING REC		<b>)</b> (R		ort all st LE SIZE	rın	gs set in well) CEMENTING RECORD AMOUNT PULLED			PULLED				
				•													<u></u>		
										<u> </u>									
24. SIZE	TOP		BO	ГТОМ	LIN	ER RECORD	ENT	SCR	REEN	1	25. SIZ			NG REG		PACK	ER SET		
																	-		
26. Perforation r	ecord (inter	erval, size	and nu	nber)		<u> </u>		27.	AC	D. SHOT.	FR.	ACTURE, CE	MEN	IT. SOU	JEEZE.	ETC.			
										INTERVAL		AMOUNT A							
													• •						
28.		r	<u> </u>							<b>FION</b>			(D						
Date First Producti	on		Product	ion Met	10d ( <i>F1</i> 0	owing, gas lift, pi	umpin	g - Siz	e an	a type pump	)	Well Status	(Prod	a. or sni	(I-IN)				
Date of Test	Hours	Fested	Cho	oke Size		Prod'n For Test Period		Oil ·	- Bbl		Ga	s - MCF	w.	ater - Bb	il.	Gas - C	il Ratio		
Flow Tubing Press.	Casing	Pressure		culated 2 ur Rate	24-	Oil - Bbl.		·	Gas	- MCF		Water - Bbl.		Oil G	avity - A	PI - <i>(Cor</i>	r.)		
29. Disposition of	Gas <i>(Sold</i>	, used for	fuel, ven	ted, etc.)		I		I					30. T	est Witi	iessed By	/			
31. List Attachmen	īts																		
32. If a temporary	pit was us	sed at the v	vell, atta	ch a plat	with th	e location of the	tempo	orary p	oit.	SEE ATTA	CHE	D							
33. If an on-site bu			-			Latitude 3	36.169	17 N		Longitude	107	38330 W N/	AD 19	27 1982	 3X				
I hereby certify	that the	e inform	ation s			h sides of this	form	is tr	rue d	and comp	lete	to the best o	f my	knowle	edge an	nd belief	c		
Signature				Printee Name		Goodwin	Т	itle F	Regi	ılatory Te	ch.		Da	ite					
E-mail Address	JGood	win@lo	gosope	rating.	com														



# Pit Closure Form:

Date: $5814$
Well Name: LOGOS 8
Footages: <u>1640' FNL &amp; 2250' FEL</u> Unit Letter: <u>G</u>
Section: <u>5</u> , T- <u>22N</u> , R- <u>5W</u> , County: <u>SANDOVAL</u> State: <u>NM</u>
Contractor Closing Pit:USS

Construction Inspector	
Inspector Signature:	Wayne At
Date: <u>5-8-14</u>	_



UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF INDIAN AFFAIRS** JICARILLA AGENCY P.O. BOX 167 DULCE, NEW MEXICO 87528



IN REPLY REFER TO: Energy & Minerals Management

JAN 2 1 2014

Ms. Tamra Sessions Logos Resources, LLC 4001 North Butler Boulevard, Building 7101 Farmington, New Mexico 87401

Dear Ms. Sessions:

This is in response to your request, dated January 13, 2014, for permission to perform work on the following location, which is on Tribal Surface:

#### Lease No. 424, Logos #8:

Located in Section 5, Township 22 North, Range 5 West, N.M.P.M. Sandoval County, New Mexico (API No. 30-043-21156).

#### Scope of Work:

Pit closure extension of 90-days (ending on April 22, 2014), due to inclement weather conditions.

The Bureau of Indian Affairs, Jicarilla Agency, hereby grant Logos Resources, LLC and its contractor's permission to perform work of the above indicated location. Please submit an affidavit of completion and/or final report when completed.

If you should have any questions or concerns, please contact Mr. Kurt Sandoval, Acting Realty Officer, at (575) 759-3936.

Sincerely.

1/MM Wight

Jicarilla Oil and Gas Administration CC:

RECEIVED ARES ON



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF INDIAN AFFAIRS JICARILLA AGENCY P.O. BOX 167 DULCE, NEW MEXICO 87528



IN REPLY REFER TO: Energy & Minerals Management

APR 8 2014

Ms. Tamra Sessions Logos Resources, LLC 4001 North Butler Boulevard, Building 7101 Farmington, New Mexico 87401

Dear Ms. Sessions:

This is in response to your request, dated **April 7, 2014,** for permission to perform work on the following location, which is on Tribal Surface:

#### Lease No. 424, Logos #8:

Located in Section 5, Township 22 North, Range 5 West, N.M.P.M. Sandoval County, New Mexico (API No. 30-043-21156).

#### Scope of Work:

Notice of temporary pit closure operations beginning April 10, 2014. Drill cuttings will be buried in reserve pit.


The Bureau of Indian Affairs, Jicarilla Agency, hereby grant Logos Resources, LLC and its contractor's permission to perform work of the above indicated location. Please submit an affidavit of completion and/or final report when completed.

If you should have any questions or concerns, please contact Mr. Kurt Sandoval, Acting Realty Officer, at (575) 759-3936.

Sincerely,

full full for the second secon

cc: Jicarilla Oil and Gas Administration







UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF INDIAN AFFAIRS** JICARILLA AGENCY P.O. BOX 167 DULCE, NEW MEXICO 87528



IN REPLY REFER TO: Energy & Minerals Management

APR 1 4 2014

Ms. Tamra Sessions Logos Resources, LLC 4001 North Butler Boulevard, Building 7101 Farmington, New Mexico 87401

Dear Ms. Sessions:

This is in response to your request, dated April 11, 2014, for permission to perform work on the following location, which is on Tribal Surface:

#### Lease No. 424, Logos #8:

Located in Section 5, Township 22 North, Range 5 West, N.M.P.M. Sandoval County, New Mexico (API No. 30-043-21156).

#### Scope of Work:

Additional (2<sup>nd</sup>) 30-day extension of pit closure operations, ending on May 29, 2014, due to inclement weather conditions.

The Bureau of Indian Affairs, Jicarilla Agency, hereby grant Logos Resources, LLC and its contractor's permission to perform work of the above indicated location. Please submit an affidavit of completion and/or final report when completed.

If you should have any questions or concerns, please contact Mr. Kurt Sandoval, Acting Realty Officer, at (575) 759-3936.

Sincerely,


Methight Superintendent

CC: Jicarilla Oil and Gas Administration



### **Reclamation Form**:

Date: 8 38 14
Well Name: <u>LOGOS 8</u>
Footages: <u>1640' FNL &amp; 2250' FEL</u> Unit Letter: <u>G</u>
Section: <u>5</u> , T- <u>22N</u> , R- <u>5W</u> , County: <u>SANDOVAL</u> State: <u>NM</u>
Reclamation Contractor: <u>ACG</u>
Reclamation Start Date: <u>5914</u>
Reclamation Complete Date: $5 28 14$
Road Completion Date: $5 28 14$
Seeding Date: <u>8 38 14</u>
PIT MARKER STATUS
(When Required) Picture of Marker set needed
Date Marker Placed: <u>82514</u>
Latitude: 36.16917N
Longitude: 101.38330
Date Pit Manifold Removed: <u>N/A</u>
Construction Inspector Signature: Day 17th
Date Inspected: <u>8-28-14</u>





			Tempor	ary Pit Wee	kly Inspection	on Form	-					
WELL NAME:	OGOS 8	<u></u> .•	à.	API NO:	30-043-21156							
LEGALS:	Section:	5	Township:	22N	Range:	5W						
Drilling RD Date:	10/18/2013											
	Ramsey	Ramsey	Ramsey	-		Ramsey		Ramsey	Ramsey			Ramsey
Inspector's Name	Hatalie	Hatalie	Hatalie	Hatalie	Hatalie	Hatalie	Hatalie	Hatalie	Hatalie	Hatalie	Hatalie	Hatalie
WEEK #	1	2	3	4	-	6	7	. 8	-	-		12
DATE Well sign on location	10/28/13	11/04/13	11/11/13	11/18/13	11/27/13	12/02/13	12/09/13	12/16/13	12/23/13	12/30/13	01/06/14	01/07/14
(Y/N)	Y	Y	Y	Y	Y ·	Y	Y	Y	Y	Y	Y	Y
Any liner breeches												
(Y/N)	N	N	N	N	N	N	N	N	N	N	N	N
Any fluid seeps/spills						.,			IN IN	N	N	N
(Y/N) HC's on top of temp.	N	N	N	N	N	N	N	N		IN		
pit (Y/N)	N	N	N	N	N	N	N	N	N	N	N	N
Temp pit free of misc.								<u></u>				
Solid												
Waste/Debris(Y/N)	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y
Discharge Line												
Integrity Good (Y/N)	Y .	Υ	Y	Y	Υ	Y	Y	Y	Y	Υ	у	N
Fence Integrity Good (Y/N)	V	v	l <sub>Y</sub>			V		Y		v		v
Any Dead Wildlife/	Y	Ŷ	Y	N	N	Y	N	Y	Y	Y		<u> </u>
Stock (Y/N)	N	N <sup>1</sup>	N	N	N	N	N	N	N	N	N	N
Freeboard to be 2' or										-		
> Est. (ft)	N	N	Y	Y (5')	Y (8')	Y (8')	Y (5')	Y (6')	Y (6')	Y (6')	Y (9')	Y (11')
Was the OCD												
contacted (Y/N)	N	N	N	N	N	N	N	N	N	N	N	N
Pictures taken (Y/N)	Y	Y	l <sub>Y</sub>	Y	Y	Y	Y	Y	ly l	Y	Y	Y
					,	·	·					·
		-	······									· ·
-												
							5'					
			West side pit	Crew moving			Clearance/Ne	6'		· ·		
			by blwon	red blow	8'		ed fixed on	Clearance/Fe				
Comments:		Back flush	down tank		Clearance/we	8'	the	nce needs to		1		
	Back flush	fuild & mud	need	and pull out T	· ·	Clearance/So	Southwest	be repulled				
	fuild from	from	clearing/stain	post/needs	repulled & T	utwest side	side, pul out	on the			1	
	wellhead in	wellhead in	dirt from	fixing/5'	post	needs to be	when moving					
No. Contract Contract Contract	the pit	pit	blow down	clearance	straightened	fixed	frac tank	corner	6' Clearance	6' Clearance	9' Clearance	11' Clearance

•

			Tempor	ary Pit Wee	kly Inspecti	on Form						
WELL NAME:	.OGOS 8			API NO:	30-043-21156							
LEGALS:	Section:	5	Township:	22N	Range:	5W						
Drilling RD Date:	10/18/2013											
	· · · · · · · · · · · · · · · · · · ·		,			·····	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	1	·····		
Inspector's Name	Ramsey Hatalie	Ramsey Hatalie	Ramsey Hatalie	1 '	Ramsey Hatalie	Ramsey Hatalie	Ramsey Hatalie	Ramsey Hatalie	Ramsey Hatalie	Ramsey Hatalie		
WEEK #	13										23	24
DATE	01/14/14					04/05/14	04/12/14			05/13/14	23	24
Well sign on location	01/14/14	01/25/14	02/15/14	03/03/14	03/24/14	04/05/14	04/12/14	04/22/14	04/28/14	05/13/14		
(Y/N)	Y	Y	Y	l <sub>Y</sub>	Y	Y	v	Y	Y	v		
Any liner breeches	<u> </u>	<u> </u>			* 	,	<u>                                      </u>	<u> -</u>	<u> </u>	<u> </u>		
(Y/N)	N	N	N	N	N	N	N	N	N	N		
Any fluid seeps/spills					N	IN						
(Y/N)	N	N	N	N	N	N	N	N	N	N		
HC's on top of temp.							<u> </u>	<u> </u>				
pit (Y/N)	N	N	N	N	N	N	N	N	N	N		
Temp pit free of misc.				·····								
Solid												
Waste/Debris(Y/N)	Y	Y	ly	Y	Y	ly l	Y	ly l	Y	N		
Discharge Line						-	·					·······
Integrity Good (Y/N)	Y	Y	N	N	N	N	N	N	N	N I		
Fence Integrity Good		-										
(Y/N)	Y	Y	Y	Υ	Y	Y	Y	Y	Y	N		
Any Dead Wildlife/												
Stock (Y/N) Freeboard to be 2' or	N	N	N	N	N	N	N	N	N	N		
> Est. (ft)			× (4 O))			14.20			v			
Was the OCD	Y (9')	Y (9')	Y (10')	Y (10')	Y (11')	Y (12')	Y (9')	Υ	Y	N		
contacted (Y/N)	N	N	N	N	N	N	N	N	N	N		
			14				<u></u>					
Pictures taken (Y/N)	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y		
					·			·	· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·	
		}	J	J	ļ	J	9'		J	ļ		
							Glearnce/Cre					
Comments:								Crew in	Crowworking	Completion,		
							w dumped	1	-			
							some mud	process of	-	crew finished		
						121 01	from another	, v	pit about	back fill on		
	9 Clearance	9' Clearance	10' Clearance	10' Clearance	11' Clearance	12' Clearance	location	earth pit	75% done	the earth pit		

.



4001 N. Butler Ave Farmington, NM 87401 Phone: (505) 436-2627 Fax: (505) 832-3095

Date: September 30, 2014

To: NMOCD

Re: Pit Closure Filings for WPX

Dear NMOCD,

Logos Operating, LLC (289408) is filing this pit closure report on behalf of the new operator, WPX Energy Production, LLC (120782), as part of a transition service agreement between Logos and WPX.

Regards, modul

Jarhie Goodwin Regulatory Technician



4001 N. Butler Ave Farmington, NM 87401 Phone: (505) 436-2627 Fax: (505) 832-3095

Date: October 21, 2014

To: NMOCD

**OIL CONS. DIV DIST. 3** 

OCT 2 2 2014

Re: Closure Permit #12239 Logos 8 API 30-043-21156

Dear NMOCD,

Logos Operating, LLC (289408) has reviewed their information regarding your email request dated 10/20/14 for general issues encountered on our submitted closure report.

- No copy of Final 418.1 sample results included with permit.
  - Please find attached the Final 418.1 sample results.
  - o Please find attached 418.1 sample dated 3/31/14 TPH 1500

Regards,

Groodww mu

Jamie Goodwin Regulatory Technician



#### EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:	Logos Operating, LLC	Project #:	12035-0038
Sample No.:	1	Date Reported:	5/12/2014
Sample ID:	Logos #8	Date Sampled:	3/31/2014
Sample Matrix:	Soil	Date Analyzed:	3/31/2014
Preservative:	Cool	Analysis Needed:	TPH-418.1
Condition:	Cool and Intact		

		Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

Total Petroleum Hydrocarbons1,5005.0

ND = Parameter not detected at the stated detection limit.

References: Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water and Waste, USEPA Storet No. 4551, 1978.

Comments: Logos #8

Instrument calibrated to 200 ppm standard and zeroed before each sample.

Analyst

Sheena Leon Printed

ama Review

Toni McKnight, EIT Printed

 Ph (505) 632-0615
 Fx (505) 632-1865

 Ph (970) 259-0615
 Fr (800) 362-1879



Cal. Date: 31-Mar-14

Parameter	Standard Concentration mg/L	Concentration Reading mg/L	
ТРН	100		
	200	204	
	500		
	1000		

The accepted percent relative deviation (%RSD) of the calibration factor is less than 20% over the working range.

Analyst

Sheena Leon Print Name

on Review

Toni McKnight, EIT Print Name

5/12/2014

5/12/2014

Date

Date

Ph (505) 632-0615 Fx (505) 632-1865