

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Elm Ridge Exploration Co LLC	Contact Amy Archuleta	OIL CONS. DIV DIST. 3 OCT 21 2014
Address PO BOX 156	Telephone No. 505-632-3476 x 201	
Facility Name Dome Federal 24-21	Facility Type Oil Well	
Surface Owner BLM	Mineral Owner BLM	API No. 30-045-25244

LOCATION OF RELEASE

Unit Letter C	Section 24	Township 23N	Range 08W	Feet from the 510	North/South Line NORTH	Feet from the 1920	East/West Line WEST	County San Juan
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

Latitude 36.218310 Longitude -107.63582

NATURE OF RELEASE

Type of Release Oil and Water	Volume of Release 25 Bbls	Volume Recovered 25 Bbls
Source of Release Production Tank	Date and Hour of Occurrence 10-12-14 Time Unknown	Date and Hour of Discovery 10-13-14 8AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell	
By Whom? Richard Graves	Date and Hour 10-13-14 9AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A



Describe Cause of Problem and Remedial Action Taken.*

This well had recently had a joint of bad tubing replaced and the well started producing more than anticipated. The Pumper didn't check the well over the weekend.

Describe Area Affected and Cleanup Action Taken.*

All the oil and water was released inside the berm. We vacuumed up the remaining liquid and removed the contaminated soil and took it to the Envirotech Land Farm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Amy Archuleta		Approved by Environmental Specialist: 	
Title: Sr. Regulatory Supervisor		Approval Date: 11/19/14	Expiration Date:
E-mail Address: aarchuleta@elmridge.net		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10-20-14 Phone: 505-632-3476			

* Attach Additional Sheets If Necessary

Handwritten: 143 2335948