Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Jun 19, 2008 WELL API NO.	
District II	OIL CONSERVATION DIVISION		30-039-25265	
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Le	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u>	Santa Fe, NM 87505		6. State Oil & Gas Le	FEE
1220 S. St. Francis Dr., Santa Fe, NM 87505			FEE	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name San Juan 30-5 Unit	
	Gas Well 🛛 Other P&A		8. Well Number 246	
2. Name of Operator			9. OGRID Number	
ConocoPhillips Company			217817	
3. Address of Operator P.O. Box 4289, Farmington, NM 87499-4289			10. Pool name or Wildcat Basin FC	
4. Well Location			Dash	
Unit Letter L : 201	feet from the <u>South</u>	ine and53	feet from the	West line
Section 26		ge 5W		ba County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 'GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A				
OTHER:		THER:		
	leted operations. (Clearly state all per		nd give pertinent dates, in	cluding estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
10/13/14: Ran CBL, TOC @ 300' w/ shoe @ 310'. Procedure states to do all inside balance plugs. After review, John Durham from OCD				
Who was on site said to perf @ 290'& do inside/outside plug to surface and an inside plug from 361' to surface.				
The subject well was P7A'd on 10/1	5/14 per the above notification & the a	ttached report.	Approved for plugging of	wellbore only.
	PNR Or		Liability under bond is ret	
	PNIC OI	my_	Receipt of C-103 (Subsequ Plugging) which may be fo	
Spud Date:	Rig Release	d Date: V	page under forms	
			www.emnrd.state.us/ocd	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE				
Type or print name Kenny Davis E-mail address: kenny.r.davis@conocophillips.com PHONE: 505-599-4045				
For State Use Only DEPUTY OIL & GAS INSPECTOR				
ADDROVED DV:	TITLE			TE 11/7/14
APPROVED BY: Conditions of Approval (if any):			<u>RIGT #3.</u> DA	
contantiono or reprovar (n any).	ŔV			

,

2 ylb

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Conoco Phillips San Juan 30-5 Unit 246

October 15, 2014 Page 1 of 1

2011' FSL and 531' FWL, Section 26, T-30-N, R-5-W Rio Arriba County, NM Lease Number: FEE API #30-039-25265

Plug and Abandonment Report Notified NMOCD and BLM on 10/8/14

Plug and Abandonment Summary:

- **Plug #1** with CR at 3053' spot 106 sxs (125.08 cf) Class B cement inside casing from 3053' to 2488' to cover the Liner top, Fruitland, Kirtland and Ojo Alamo tops.
- Plug #2 with 29 sxs (34.22 cf) Class B cement inside casing from 1533' to 1379' to cover the Nacimiento tops.
- Plug #3 with 85 sxs (100.3 cf) Class B cement inside casing from 361' to surface squeeze 17 sxs in annulus. Tag TOC at 11'.
- **Plug #4** with 26 sxs Class B cement top off casings and install P&A marker with coordinates N 36° 49.916'/W 107° 20.033'.

Plugging Work Details:

- 10/9/14 Rode rig and equipment to location. Spot in and RU. SDFD.
- 10/10/14 Stand by due to muddy road conditions.
- 10/13/14 Bump test H2S equipment. Check well pressures: casing 60 PSI, tubing 30 PSI and bradenhead 0 PSI. RU relief lines and blow well down: ND wellhead. RU Cameron pressure equipment. Pressure test BOP blind 2-3/8" rams to 300 PSI and 1300 PSI, OK. Pull tubing hanger. TOH and tally 1 jnt, 4' sub, 49 stands, 1 jnt, 4' sub, 1 jnt, FN of 2-3/8" tubing EUE 3216' (101 jnts). PU 7" string mill to 3083'. TIH with 7" DHS CR and set at 3053'. Pressure test tubing to 1000 PSI, OK. Establish circulation. Pressure test casing to 800 PSI. SI well. SDFD.
- 10/14/14 Open up well; no pressures. RU relief lines. Function test. RU A-Plus wireline. Ran CBL from 3053' to surface, calculated TOC at 300'. Establish circulation. Spot plugs #1 and #2. RU A-Plus wireline. Perforate 3 HSC squeeze holes at 290'. Casing pressured up to 1000 PSI establish rate of 2 bpm at 1000 PSI. Bradenhead pressured up to 800 PSI. Wait on orders. Note: J. Morris, MVCI approved to spot balance plug. Establish circulation. Spot plug #3 with TOC at surface. SI well. SDFD.
- 10/15/14 Bump test H2S equipment. Open up well; no pressures. TIH and tag TOC at 11'. ND BOP and kill spool. Dig out wellhead. RU High Desert. Cut off wellhead: Found cement down 2' in 7" casing and 13' in annulus. Spot plug #4 to top off casings and install P&A marker with coordinates N 36° 49.916'/W 107° 20.033'. RD and MOL.

Jim Morris, MVCI representative, was on location. John Durnham, NMOCD representative, was on location.