



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrmd.state.nm.us/ocd/District III/3district.htm](http://emrmd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV DIST. 3

JUN 05 2013

Date of Test 5-3-13 Operator Elm Ridge Exploration CO LLC API #30-039-06552

Property Name Candado Well No. 002 Location: Unit P Section 9 Township 26N Range 07W

Well Status(Shut-In or Producing) Initial PSI: Tubing 98 Intermediate Casing 123 Bradenhead 25

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>2</u>		<u>123</u>		
10 min	<u>1</u>		<u>123</u>		
15 min	<u>1</u>		<u>123</u>		
20 min	<u>1</u>		<u>123</u>		
25 min	<u>1</u>		<u>123</u>		
30 min	<u>1</u>		<u>123</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	<u>✓</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH ✓ SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 25 INTERMEDIATE

REMARKS:

Steady flow of fresh water

By Jason Herbig

Witness

Pumper
(Position)

E-mail address