



Burlington Resources,
A wholly owned subsidiary of ConocoPhillips

San Juan Business Unit
3401 E. 30th Street
Farmington, NM 87402-4289
(505) 326-9700

September 24, 2014

Mr. David Aguinaga
Water Resources Section (6EN-WR)
U.S. Environmental Protection Agency
1445 Ross Avenue
Dallas, TX 75202-2733

RCVD SEP 25 '14
OIL CONS. DIV.
DIST. 3

Re: **Submittal: Mechanical Integrity Test completed at the Ute No. 1 Salt Water Disposal, Permit No. 06SNMU1P9024, San Juan County, New Mexico**

Dear Mr. Aguinaga,

Pursuant to EPA Permit No. 06SNMU1P9024, Part I, Section B, Paragraph 1, Operating Requirements for the Ute 1 Salt Water Disposal (SWD) injection well, API# 3004511475, T32N R14W Section 11, San Juan County, New Mexico; ConocoPhillips Company (COPC) would like to provide the Mechanical Integrity Test (MIT) results that were completed on September 17, 2014 at the Ute 1 SWD wellhead location. The successful MIT was witnessed by Mr. Rick Davis, EPA Inspector Region 6 and completed by High Tech Rental Tools. The completion and submission of this MIT meets permit requirements for the required five (5) year MIT. Please see the attached MIT chart results for submittal and review.

If you have any questions or need additional information, please contact me or Robert Stuard.

Sincerely,

Gwen Frost
ConocoPhillips
Environmental Coordinator

Attachment: Ute 1 SWD MIT Chart Results

Cc:

Mr. Willie Lane – U.S. EPA Region 6
Mr. Dale Selgrath – U.S. EPA Region 6
Mr. Scott Clow – Ute Mountain Ute Tribe
Monica Kuehling – NMOCD
Mr. Terry Nelson – ConocoPhillips
Mr. Robert Stuard – ConocoPhillips

* Test does not comply with 19.15.26.11.A NMAC BP

DIST. 3

