



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

APR 24 2013

Date of Test 4/16/2013 Operator WPX Energy API #30-0 3922778

Property Name Rosa Unit Well No. 085 Location: Unit A Section 20 Township 31N Range 05W

Well Status (Shut-In or Producing) Initial PSI: Tubing 139 Intermediate 0 Casing 154 Bradenhead 4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	0	154		
10 min	0	0	154		
15 min	0	0	154		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓ in 1 second
Nothing	✓
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

After 24 hour shut-in performed Test the bradenhead blew down to nothing.
Left both bh and int valves open after test.

By Stacey McLendon
Field Technician
(Position)

Witness _____

E-mail address stacey.mclendon@wpxenergy.com