



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12-16-14 Operator ConocoPhillips API #30-0 39-24549
Property Name San Juan 31-6 SUD Well No. 301 Location: Unit 6 Section 6 Township 30 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 1040 Intermediate 81 Casing -8 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	81	-8	70	-8
10 min	0	81	-8	69	-8
15 min	0	81	-8	69	-8
20 min				16	-8
25 min				10	
30 min				5	-8

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

OIL CONS. DIV DIST. 3
DEC 16 2014

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

0

INTERMEDIATE

7

REMARKS:

BH - down in 5 seconds to clear
Int - Blew head while 30 min test

By

(Position)

Witness

E-mail address

Re-test in 6 months
depending on analysis
gas analysis Int. DA