

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company ConocoPhillips	Contact Lindsay Dumas
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 599-4089
Facility Name: San Juan 29-6 245	Facility Type: Gas Well

Surface Owner: Public	Mineral Owner: SF-078278	API No. 3003924910
------------------------------	---------------------------------	---------------------------



LOCATION OF RELEASE

Unit Letter B	Section 08	Township 29N	Range 06W	Feet from the 852'	North/South Line North Line	Feet from the 2320'	East/West Line East Line	County San Juan
-------------------------	----------------------	------------------------	---------------------	------------------------------	---------------------------------------	-------------------------------	------------------------------------	---------------------------

Latitude **36.74505** Longitude **-107.4846**

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 260 MCF	Volume Recovered 0 MCF
Source of Release Wellhead	Date and Hour of Occurrence 11/7/2014 10:50 AM	Date and Hour of Discovery 11/10/2014 8:30 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The well was found open to atmosphere, the lubricator cap was missing and the plunger was found 3 feet away from the wellhead. COP will investigate the cause of this incident.		
Describe Area Affected and Cleanup Action Taken.* No soil contamination.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lindsay Dumas	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 12/29/14	Expiration Date:
E-mail Address: Lindsay.Dumas@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/18/2014 Phone: (505) 599-4089		

* Attach Additional Sheets If Necessary

#NCS 143 633 1012

①