State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr.

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1220 S. St. Fran	cis Dr., Santa	a Fe, NM 8750	5			st. France, NM 875							
·		· · · · · ·	Rel			<u> </u>	orrective A	ction			* • #		
						OPERA			🛛 Initi	al Report	\boxtimes	Final Report	
Name of Co	mnany A	RP Producti	any LLC	~ ~ ~	OPERATOR Initial Report Final Rep Contact Randy L. Madison						т шаг кероп		
		t., Raton, NM		Telephone No. Office 575-445-6706 Cell 575-420-1120									
Facility Nar					e Gas Well								
			.1							20.007.0	0100		
Surface Ow	ner verme	o Park Ran	cn	Mineral	Jwner A	PR Product	tion Company, I	LLC	<u>API NO</u>	b. 30-007-2	0108		
	,	r				OF REI							
Unit Letter Section Township Range Feet from the North						South Line	Feet from the	East/We	t/West Line County				
Ν	N 32 31N 18E 742' S						outh 1752			West Colfax			
		Lat	itude N	36.872886	Lor	gitude	W 105.055666						
	1	Lu	induc										
Tune of Dala	asa Droduo	ed Water			URE	OF REL			/ aluma I	Decoursed 0	<u> </u>		
Type of Release		lve froze and	busted on	a vent line					Volume Recovered 0 Date and Hour of Discovery				
Source of Me.	icuse i va		Cusicu Oli	a vone mie		Unknown			2/9/14 (covery		
Was Immedia	ate Notice (If YES, To Whom?							
			Yes 🗌] No 🛛 Not R	equired	I Cory Smith							
By Whom? R						Date and Hour 12/9/14 @1130							
Was a Water	course Read	ched?	Yes 🗵	1 No		If YES, Volume Impacting the Watercourse.							
										<u>_</u>			
If a Watercou	irse was Im	pacted, Descr	ibe Fully.	*				6	11 CON	IS. DIV DI	107 1	5	
								U U	IL UUN	19. DIA DI	131. d	5 ,	
									DEI	C 16 201	4		
Describe Cau	se of Probl	em and Reme	dial Actio	n Taken.*		·							
				ased the produce	d water.	The valve wa	as replaced.						
Describe Are													
		ad and the lea	se road. 1	None of the produ	ced wate	r was recover	red. See attached	water ana	lysis for	the D-20 we	ll whic	h is where all	
of the water c	came from.												
I hereby certi	fy that the i	information gi	ven above	is true and comp	lete to th	e best of my	knowledge and u	nderstand	that purs	suant to NM	OCD ri	iles and	
regulations al	I operators	are required t	o report ai	nd/or file certain r	elease no	otifications a	nd perform correct	tive action	ns for rel	eases which	may er	ndanger	
public health	or the envi	ronment. The	acceptant	ce of a C-141 repo	ort by the	NMOCD m	arked as "Final Re on that pose a thre	eport" doe	s not rel	ieve the oper	ator of	liability	
							e the operator of r						
federal, state,							F						
							OIL CONS	SERVA	TION	DIVISIC)∦/		
	\sim							7	//				
Signature: 7	Fandy	J.M.	t-des-			Approved by Environmental Specialist:							
			· <u>-</u> ,		′	Approved by	Environmental Sp	sectarist.	Can	y y	1/2	4	
Printed Name	: Randy L.	Madison					, 2			\searrow	\sim (
Title: EHS Specialist						Approval Date: 12/15 Expiration Date:							
						-pp.o./ur.but			Filmion				
E-mail Addre	ess: rmadis	on@atlasener	gy.com		(Conditions of	Approval:			Attached			
Date 12/9/14	L		F	Phone: 575-445-6	706								
Attach Addit		ets If Necess		none. 575-445-0	,	HAN	S 1/	<u>)</u>					
			2			++-1UC	S 15018	X 42	807	7			

* Attach Additional Sheets If Necessary

Rocky Mountain Region 1675 Broadway, Suite 1500 Denver, CO 80202 (303) 573-2772 Lab Team Leader - Sheila Hernandez (432) 495-7240

Water Analysis Report by Baker Petrolite

EL PASO E & P	Sales RDT:	44625
ROCKY MOUNTAINS	Account Manager:	TY CLINESMITH (575) 447-0621
RATON, NM	Sample #:	50952
VERMEJO PARK RANCH 'D'	Analysis ID #:	119142
20	Analysis Cost:	\$90.00
UNKNOWN		
WELLHEAD		
	ROCKY MOUNTAINS RATON, NM VERMEJO PARK RANCH 'D' 20 UNKNOWN	ROCKY MOUNTAINSAccount Manager:RATON, NMSample #:VERMEJO PARK RANCH 'D'Analysis ID #:20Analysis Cost:UNKNOWN

Sumi	mary	Analysis of Sample 50952 @ 75 ℉							
Sampling Date:	03/30/12	Anions	mg/l	meq/l	Cations	mg/l	meq/l		
Analysis Date:	04/14/12	Chloride:	354.0	9.99	Sodium:	538.9	23.44		
Analyst:	STACEY SMITH	Bicarbonate:	799.0	13.09	Magnesium:	0.8	0.07		
TDC (mm/l ar m/m2)	1728.4	Carbonate:	23.0	0.77	Calcium:	6.5	0.32		
TDS (mg/l or g/m3):		Sulfate:	3.0	0.06	Strontium:	0.3	0.01		
Density (g/cm3, tonn Anion/Cation Ratio:	,	Phosphate:			Barium:	0.7	0.01		
Amon/Gauon Ratio.	0.99999990	Borate:			lron:	0.2	0.01		
		Silicate:			Potassium:	2.0	0.05		
					Aluminum:				
Carbon Dioxide:		Hydrogen Sulfide:			Chromium:				
Oxygen:		pH at time of sampling:			Copper:				
Comments:					Lead:				
		pH at time of analysis:		8.38	Manganese:	0.025	0.		
		pH used in Calculation:		8.38	Nickel:				
				N .					
	•								

Cond	ition <u>s</u>		Values Calculated at the Given Conditions - Amounts of Scale in Ib/1000 bbl											
Temp Gauge Press.		Calcite CaCO ₃		Gypsum CaSO ₄ *2H ₂ 0		Anhydrite CaSO ₄		Celestite SrSO ₄		Barite BaSO ₄		CO ₂ Press		
ፑ	psi	Index	Amount	Index	Amount	Index	Amount	Index	Amount	Index	Amount	psi		
80	0	0.46	3.15	-4.29	0.00	-4.36	0.00	-3.87	0.00	-0.41	0.00	0.05		
100	0	0.51	3.50	-4.29	0.00	-4.30	0.00	-3.84	0.00	-0.54	0.00	0.08		
120	0	0.57	3.85	-4.29	0.00	-4.21	0.00	-3.81	0.00	-0.65	0.00	0.12		
140	0	0.63	4.20	-4.27	0.00	-4.11	0.00	-3.76	0.00	-0.73	0.00	0.17		

Note 1: When assessing the severity of the scale problem, both the saturation index (SI) and amount of scale must be considered.

Note 2: Precipitation of each scale is considered separately. Total scale will be less than the sum of the amounts of the five scales.

Note 3: The reported CO2 pressure is actually the calculated CO2 fugacity. It is usually nearly the same as the CO2 partial pressure.