Submit One Copy To Appropriate District	State of New Me	evico	Form	C-103
Office District I	ice France Minerals and Natural Description		Revised November 3, 2011	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
District II 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION			30-031-20150	
District III 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM			o. State on & Sas Zease No.	
87505	ES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement N	Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Santa Fe Railroad	
1. Type of Well: Oil Well Gas Well Other OIL CONS. DIV DIST. 3			8. Well Number #23	
2. Name of Operator			9. OGRID Number	
Dominion Production Company, LLC  NOV 9 3 2014			291567	
3. Address of Operator			10. Pool name or Wildcat	
1414 W Swann Av, Suite 100, Tampa, FL 33606			Hospah	
4. Well Location				
	the N line and 1330'feet from the			
	N Range 9W NMPM McKin			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6900' GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS. PAND A DULL OR ALTER CASING  MULTIPLE COMPL  CASING/CEMENT JOB				
FOLE ON ALTEN CASINO	WOLTH LL COMPL	CASINO/CEMEN		
OTHER:			eady for OCD inspection after P&A	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.  Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
Rat hole and cellar have been fille  A steel marker at least 4" in diame	-			
A steel market at least 4 in diame	ter and at least + above ground	ievei nas been sei m	teolerate. It shows the	
	E NAME, WELL NUMBER, A TOWNSHIP, AND RANGE.		JARTER/QUARTER LOCATION OF THE STATE OF THE	<u> </u>
	D ON THE MARKER'S SUR			
	early as possible to original grou	nd contour and has	been cleared of all junk, trash, flow lin	nes and
other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
☐ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator	or's pit permit and closure plan.	All flow lines, prod	uction equipment and junk have been	removed
from lease and well location.	have been removed. Dortable be	sas hava haan rama	yed (Poured ancits congrete bases do	not have
All metal bolts and other materials to be removed.)	have been removed. Fortable ba	ses have been femo	ved. (Poured onsite concrete bases do	not nave
All other environmental concerns	have been addressed as per OCD	rules.		
	abandoned in accordance with	9.15.35.10 NMAC	All fluids have been removed from n	ion-
retrieved flow lines and pipelines.				1 11
If this is a one-well lease or last re location, except for utility's distribution		cal service poles and	d lines have been removed from lease	and well
location, except for utility's distribution	i mirastructure.			•
When all work has been completed, ret	un this form to the appropriate I	District office to sch	edule an inspection.	
SIGNATURE	TITLE	President	DATE October 27	7, 2014
TYPE OR PRINT NAME David Bu	rns F_MAII ·	davidburns@domi	nionproduction.com PHONE: 832-54.	5-4600
For State Use Only	/ - +	_		
1/1/an100		CRUIT NIF R	GAS INSPECTOR	VII A
APPROVED BY: 10 Bruch	TITLE_	DISTR	DATE 12-10	<u>114</u> 10
	()			