OIL CONS. DIV DIST. 3

				DEC 1 1 2014			
Submit One Copy To Appropriate District Office	State of No.	ew Mex	kico	020112014	Form C-103		
District I	Energy, Minerals ar	nd Natur	al Resources		Revised November 3, 2011		
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO.			
811 S. First St., Artesia, NM 88210	OIL CONSERVA	TION	DIVISION	30-045-21029 5. Indicate Type	e of Lesse		
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE	FEE X			
District IV	Santa Fe,	NM 87	505	6. State Oil & C			
1220 S. St. Francis Dr., Santa Fe, NM 87505							
		N OR PLU		ELLIOTT A LS			
1. Type of Well: Oil Well 🛛 G	as Well 🗌 Other		×	8. Well Number	r #2		
2. Name of Operator				9. OGRID Num	ıber		
XTO ENERGY INC.				5380 10. Pool name of	an Wildoot		
3. Address of Operator 382 CR 3100, AZTEC, NM 87410				AZTEC PICTU			
4. Well Location							
Unit Letter M : 990' feet fro	om the SOUTH line and	800' fee	et from the WE	ST line			
Section 19 Township 31N Range 11W NMPM County SAN JUAN 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 5982' GL 5982' GL 5982' GL							
12. Check Appropriate Box to In	ndicate Nature of No				The street was a street of the street of the		
			-		EDODT OF		
				UBSEQUENT R			
	PLUG AND ABANDON CHANGE PLANS				ALTERING CASING		
	MULTIPLE COMPL		CASING/CEN		FANDA L		
			ON ON OF OF				
OTHER:				is ready for OCD ins			
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. 							
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the							
OPERATOR NAME, LEAS							
UNIT LETTER, SECTION				ATION HAS BEEN	WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.							
The location has been leveled as r other production equipment.	nearly as possible to originate	inal grou	nd contour and	has been cleared of a	ll junk, trash, flow lines and		
Anchors, dead men, tie downs and	d risers have been cut off	at least	two feet below	ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with							
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed							
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have							
to be removed.)					,		
All other environmental concerns have been addressed as per OCD rules.							
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-							
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well							
location, except for utility's distributio		an crootin	iour service por	es una niñes nave been	renoved nonriedse and non		
When all work has been completed, re	eturn this form to the app	ropriate	District office t	o schedule an inspect	ion.		
SIGNATURE Kristen D.	Babcock	TITLE	REGULATOR	Y ANALYST DA	ATE <u>12/9/2014</u>		
TYPE OR PRINT NAME <u>KRISTE</u> For State Use Only							

For State Use Only			
APPROVED BY	Jonato ! Kelly	 TITLE Compliance Officer	DATE 12/30/204 N