



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9/2/05 Operator CHEVRON API #30-0 4523115  
Property Name GARRETT 13 Well No. 1 Location: Unit 12 Section 29 Township 11 Range 11  
Well Status (Shut-In or Producing) Tubing 24 Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

| TIME       | PRESSURES: |              |          | BRADENHEAD<br>FLOWED | INTERMEDIATE<br>FLOWED |
|------------|------------|--------------|----------|----------------------|------------------------|
|            | BRADENHEAD | INTERMEDIATE | CASING   |                      |                        |
| 5 minutes  | <u>0</u>   |              | <u>0</u> | Steady Flow          |                        |
| 10 minutes | <u>0</u>   |              | <u>0</u> | Surges               |                        |
| 15 minutes | <u>0</u>   |              | <u>0</u> | Down to Nothing      |                        |
| 20 minutes |            |              |          | Nothing <u>X</u>     |                        |
| 25 minutes |            |              |          | Gas                  |                        |
| 30 minutes |            |              |          | Gas & Water          |                        |
|            |            |              |          | Water                |                        |

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR 0 FRESH 0 SALTY 0 SULFUR 0 BLACK 0

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE 0

REMARKS: 1/4 BLEEDER



By MIKE DREYER  
MAINTENANCE PLANNER  
(Position)

Witness NONE - DARYL IS GONE

TOLD TO CONT  
TESTING

E-mail address MCDR@CHEVRON.COM