

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Lindsay Dumas
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 599-4089
Facility Name: San Juan 28-7 #236M	Facility Type: Gas

Surface Owner: BLM	Mineral Owner: SF-078835-A	API No. 3003926604
---------------------------	-----------------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter I	Section 06	Township 27N	Range 07W	Feet from the 1510'	North/South Line FSL	Feet from the 1245'	East/West Line FEL	County Rio Arriba
-------------------------	----------------------	------------------------	---------------------	-------------------------------	--------------------------------	-------------------------------	------------------------------	-----------------------------

Latitude 36.5997222 Longitude -107.61027

NATURE OF RELEASE

Type of Release Natural Gas/Paraffin	Volume of Release 86 MCF/5 Gal	Volume Recovered 0
Source of Release Wellhead	Date and Hour of Occurrence 12/20/2014 1:00 AM	Date and Hour of Discovery 12/22/2014 9:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* MSO arrived on location and found the lubricator approximately 10 feet from wellhead, the plunger 30 feet from wellhead and the master valve and two ball valves shut in. Well head was wiped up and affected ground raked. COP determined this to be a vandalism incident.		
Describe Area Affected and Cleanup Action Taken.* The soil will continue to be raked. COP is collecting information through a formal investigation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Lindsay Dumas</i>	OIL CONSERVATION DIVISION	
Printed Name: Lindsay Dumas	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Environmental Specialist	Approval Date: 2/6/15	Expiration Date:
E-mail Address: Lindsay.Dumas@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/29/14	Phone: (505) 599-4089	

* Attach Additional Sheets If Necessary

#NCS 1503751813

①