



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9/22/05 Operator FOUR STAR / CHEVRON API #30-0 4507637
Property Name NM COM D Well No. 1 Location: Unit 32 Township 29 Range 10
Well Status (Shut-In or Producing) Tubing 119 Intermediate NA Casing 63 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TEST START 1:10

PRESSURES:				BRADENHEAD	INTERMEDIATE
TIME	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
1:15 5 minutes	VAC		63	Steady Flow <u>X</u>	
1:20 10 minutes	VAC		63	Surges	
1:25 15 minutes	VAC		63	Down to Nothing <u>5 SEL</u>	
20 minutes				Nothing	
25 minutes				Gas <u>X</u>	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

1:30 5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

BRADEN HEAD BLED THROUGH 1/4" OPENING

By MIKE DREYER
MAINTENANCE PLANNER
(Position)

E-mail address MLDR@CHEVRON.COM

Witness NONE - CALLED EMNRD AND
DARYL HAD LEFT AND
THERE IS NO ONE TO
WITNESS

