



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8/29/05 Operator FOUR STAR CHEVRON API #30-0 4508935
Property Name FED ST COM Well No. 1 Location: Unit 32 Section 30 Township 11
Well Status (Shut-In or Producing) 436 Tubing NA Intermediate 216 Casing 31.9 Bradenhead 31.9

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
INITIAL TEST 9:20 AM

PRESSURES:

TIME	BRADENHEAD	INTERMEDIATE	CASING
9:25 5 minutes	0.8		223
9:30 10 minutes	0.7		225
9:35 15 minutes	0.6		227
9:40 20 minutes	0.6		229
9:45 25 minutes	0.6		230
9:50 30 minutes	0.6		232

BRADENHEAD
FLOWED

INTERMEDIATE
FLOWED

Steady Flow

Surges

Down to Nothing 3 MIN

Nothing

Gas X

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK


5 MINUTE SHUT-IN BRADENHEAD 1.8 INTERMEDIATE NA

REMARKS:

bled through 1/2" opening

5 min bled down to almost in 1 sec

10 min bled down in 30 sec



By MIKE PREYER
MAINTENANCE PLANNER
(Position)

Witness MAINT NONE - DARYL IS GONE
TOLD TO GO ON
AND TEST

E-mail address MLDR@CHEVRON