



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8178
FAX: (505) 334-8170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8/4 Operator FOUR STAR CHEVRON API #30-0 4909051
Property Name NM COM Well No. 1 Location: Unit 36 Section 30 Township 10
MV-95 NA 44
Well Status (Shut-In or Producing) Producing Tubing 42.5-PL Intermediate NA Casing 44 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes				Steady Flow	
10 minutes				Surges	
15 minutes				Down to Nothing	
20 minutes				Nothing <u>X</u>	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS: 1/4" BLEEDER

DARYL - TOOK ORIGINAL COPY

DUAL COMPLETION WELL

By MIKE DREYER

Witness DARYL

MAINTENANCE PLANNER

(Position)

E-mail address MLDR@CHEVRON.COM

