<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr. Santa Fo. NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division RECE Submit 1 Copy to appropriate District Office to accordance with 19.15.29 NMAC.

220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe	, NM 87505 FED 0.0)
Release Notification and Corrective Action 5		
	OPERATOR MADO	, ⊠ Initial Report □ Final Report
Subsidiary of ConocoPhillips Company	Contact Lisa Hunter TRICT	I I I I I I I I I I I I I I I I I I I
Address 3401 East 30" St, Farmington, NM Telephone No. (505) 326-9786		
Facility Name: Arizona Jicarilla A #5A Facility Type: Gas Well		
Surface Owner Jicarilla Mineral Owner Contract #124 API No. 3003922797		
LOCATION OF RELEASE		
		West Line County West Rio Arriba
Latitude <u>36.397</u> Longitude <u>-107.20642</u>		
NATURE OF RELEASE		
Type of Release Condensate & Produced Water	Volume of Release 23 bbls Condensate/5 bbls Prod Water	Volume Recovered 0 bbls
Source of Release Production Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 02/18/15 @ 12:00 pm
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required	If YES, To Whom? Bryce Hammond (Jicarilla) Cory Smith (NMOCD)	
By Whom? Lisa Hunter	Date and Hour Bryce Hammond on 02/19/15 @ 10:49 (via phone & email) NMOCD on 02/19/15 @ 10:49 (via voicemail & email)	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* While gauging tank, MSO found the tank to be 28 bbls less than last month's gauge on 1.19.15. Examined tank for sign of release & found a puddle approximately 1 ft in diameter near and outside the grade band. The area had been covered in snow until previous weekend, and a location visit the week prior did not indicate a release. Shut oil dump line, and called truck to remove the remaining fluid from tank. Tank will be cleaned and inspected for corrosion.		
Describe Area Affected and Cleanup Action Taken.* ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: Approved by Environmental Specialist: Approved by Environmental Specialist:		
FED on	Approval Date: 3/13/15	Expiration Dale:
	Conditions of Approval:	Attached
Date: February 19, 2015 Phone (505) 326-9786		

#1000 150 725 0 108