

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

FEB 19 2015

NMOCD

Form C-141  
Revised August 8, 2011

Submit copy to appropriate District Office to  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Burlington Resources Oil & Gas Company	Contact	Lindsay Dumas
Address	3401 East 30 <sup>th</sup> St, Farmington, NM	Telephone No.	(505) 599-4089
Facility Name	San Juan 28-6 155N	Facility Type	Gas

Surface Owner	BLM	Mineral Owner	SF-079050-C	API No.	3003927601
---------------	-----	---------------	-------------	---------	------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	28	28N	06W	2420'	FNL	80'	FWL	Rio Arriba

Latitude 36.63283 Longitude -107.4806

NATURE OF RELEASE

Type of Release	Hydrocarbon	Volume of Release	186 bbls	Volume Recovered	0
Source of Release	corroded hole in production tank	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	1/27/2015 @ 10:15 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Shari Ketcham(BLM) and Cory Smith (OCD) on 1/27/2015 @ 3:00pm		
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Weld on production tank was found leaking on the 2" plugged coupling located below load line. The drain line to pit was open to drain remaining fluid from tank. Well was shut in.

Describe Area Affected and Cleanup Action Taken.\*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Lindsay Dumas</i>	OIL CONSERVATION DIVISION	
Printed Name: Lindsay Dumas	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Environmental Specialist	Approval Date: 3/13/15	Expiration Date:
E-mail Address: Lindsay.Dumas@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/16/2015	Phone: (505) 599-4089	

\* Attach Additional Sheets If Necessary

#1055 15072 49715

①