

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

RECEIVED
FEB 19 2015

Release Notification and Corrective Action

OPERATOR ☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Lindsay Dumas
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 599-4089
Facility Name: Nickson 16	Facility Type: Gas

Surface Owner: BLM	Mineral Owner: SF-078431	API No. 3004520183
---------------------------	---------------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter O	Section 35	Township 26N	Range 08W	Feet from the 1075'	North/South Line FSL	Feet from the 1515'	East/West Line FEL	County San Juan
-------------------------	----------------------	------------------------	---------------------	-------------------------------	--------------------------------	-------------------------------	------------------------------	---------------------------

Latitude **36.438831** Longitude **-107.64668**

NATURE OF RELEASE

Type of Release Produced Water & Hydrocarbon	Volume of Release 18.25 bbls PW & 3.5 bbls HC	Volume Recovered 0
Source of Release corroded hole in production tank	Date and Hour of Occurrence 2/12/15 @ 1:45pm	Date and Hour of Discovery 2/12/15 @ 1:45pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.*

Corroded hole discovered near bottom of production tank. Spec truck was called to empty tank. COP will have area sampled and delineated. A final C-141 will follow.

Describe Area Affected and Cleanup Action Taken.*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Lindsay Dumas</i>	OIL CONSERVATION DIVISION	
Printed Name: Lindsay Dumas	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Environmental Specialist	Approval Date: 3/13/15	Expiration Date:
E-mail Address: Lindsay.Dumas@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/16/2015	Phone: (505) 599-4089	

* Attach Additional Sheets If Necessary

#NCS 1507249843